RESPONSE TO COMMENTS DRAFT SUMMARY FIELD REPORT STORM DRAIN REMOVAL ACTION HUNTERS POINT SHIPYARD SAN FRANCISCO, CALIFORNIA

Contract No. N62474-93-D-2151 Delivery Order No. 0061

Submitted to:

Department of the Navy Engineering Field Activity, West Naval Facilities Engineering Command 900 Commodore Drive, Building B-208 San Bruno, California 94066-2402

Submitted by:

IT Corporation 4585 Pacheco Boulevard Martinez, California 94553

OCTOBER 1998

EPA GENERAL COMMENTS

Comment

1. Please include a table summarizing the lengths of storm drain lines cleaned and the lengths not cleaned because the lines were submerged or plugged. Also provide a table with the same information for catch basins and manholes.

Response

The cleaning records for storm drain lines of Basins I through X are presented in revised Tables B-1(a) through B-10(a). Remarks were made for the storm drain lines not cleaned. The video records for records for storm drain lines of Basins I through X are presented in revised Table B-1(b) through B-10(b). The cleaning records for catch basins and manholes of Basins I through X are presented in revised Table C-1 through C-10. Remarks were made for both the cleaned and not cleaned catch basins and manholes.

Comment

2. The text does not include a correlation of disposal samples collected from either the stockpiled sediments or phase separator sediments with the storm drain areas, catch basins, or manholes from which the sediments were derived. A discussion which provides more detail about the sampling locations, frequencies, etc. pertinent to this data is necessary. It is not clear where samples were taken, the sampling frequency, how the sediment was segregated for sampling, how many samples were collected for each sediment "batch", etc.

Response

The purpose of the field activity was the removal and disposal of storm drain sediment. It was not intended to further characterize the location or the nature of the material within the storm drain system. The material removed from the storm drains was aggregated in temporary stockpiles. Samples from each of these stockpiles were taken in order to characterize the material for disposal. There is no direct correlation between these sampling results and the prior location of the sediments within the storm drain system. The intent of the disposal sampling was to provide the disposal facilities with the sampling data necessary to characterize the material removed from the storm drains in order to satisfy the acceptance criteria for that licensed facility.

Comment

3. Overall, this report does a good job of describing the work performed and includes a good log of the storm drain conditions and cleaning results.

Response

Comment is acknowledged.

EPA SPECIFIC COMMENTS

1) Page 1-2, last bullet. Please clarify. This statement is confusing and it is not clear what is conveyed in this bullet.

Response

The "lighter-colored areas" were locations where the high pressure water actually removed a small amount of the inner surface of the storm drain in addition the soil material and debris within the storm drain itself. As a result these areas appear lighter in color than the rest of the cleaned storm drain.

Comment

2) Page 1-3, last paragraph. Please define catch basins and manholes. Include illustrations and/or reference photograph(s).

Response

Reference to the distinction made between the terms "catch basin" and "manhole" are made on pages 1-3 and 2-5. Reference to vaults, manholes, and catch basins is made on page 2-5. A vault is sysnonomous with a drainage structure which includes both catch basins and manholes. Page 2-5 is being revised to replace the word "vault" with the word "drainage structure." The definition of a catch basin as explained on page 1-3 is the more traditional one. A catch basin usually has a sediment trap which collects debris by allowing materials which are heavier than water to drop out rather than be discharged to the bay. A manhole is used to access the system and typically does not have a sediment trap. An attached drawing follows these comments and responses. The drawing is a composite of Figures taken from an engineering textbook which depicts a manhole and two types of catch basins. Generally a catch basin can be distinguished at the surface by its cover which has openings to allow surface runoff to enter the system. Alternatively, a manhole cover generally has no openings. As explained in the fourth paragraph on page 2-5 the terminology in this Report reflects the more readily identifiable surface cover of the structure rather than whether the structure had a sediment trap or not. Structures with grated covers were called catch basins. Those with solid covers were called manholes. All manholes and catch basins which were accessible were cleaned regardless of their cover design.

Comment

3) Page 2-2. Please provide additional information on the sediment handling/stockpiling. Where did the water from the sediment dewatering go? Was it collected? Was it sampled? Please elaborate. Also in reviewing the photos in the appendix, it appears that the sediments were simply placed on hay bales. Again, please elaborate. Also explain that the stockpiles were located on Parcel E.

Response

All sediment and dewatering wastewater was handled according to the methods described in the letter dated 25 November 1996, from the Navy to the Agencies, copy attached. The wastewater was sampled and tested after it went through the filtration and carbon adsorption process. When the analysis results indicated that the level of contaminants exceeded 50 % of acceptable limits for disposal to the local POTW the water was transported to and discharged into the POTW at Pump Station A at Hunters Point. Until that time the water was recycled into the trucks used to clean the storm drains and reused in the cleaning process. The sediments that were removed from the storm drains were collected and stored temporarily in stockpiles of approximately 50 cubic yards each. Each stockpile was contained within a storage cell consisting of plastic liner

material lining the bottoms and sides of the cell. Hay bales were used around the four sides of each cell and the bottom liner material overlapped the hay bales on all four sides. The photo (Photo 5) in the appendix shows material being discharged into a storage cell. This cell has an additional row of hay bales on top of the bottom row of bales to keep the liner material from blowing off until the material is placed in the cell. The temporary storage cells were located in Parcel E, near the wastewater treatment area.

Comment

4) Page 2-3, second paragraph. Please elaborate on: "for reuse as makeup cleaning water." In third paragraph of this page, first sentence: typo. - need to insert "to" between words "up" and "a".

Response

See response to #3 above. As clarification, "makeup cleaning water" as used in Response #3 is water that was processed as described in the second paragraph of page 2-3 of the Report and then reused to clean the storm drain lines. Regarding the reference to a typographical error, the statement in the text is correct as shown. The trucks were backed up an inclined ramp to discharge the material into the phase separator.

Comment

5) Section 2.3, page 2-3. Note that for the sections of the lines that were submerged, these lines will need to be reevaluated during the Parcel E/Base wide FS and/or ROD and that a technical impracticability waiver may be necessary. Storm drains with submerged lines include Basins I, III, and V which cover Parcels B, C, and E.

Response

Submerged storm drain lines in Basins I, III, and V from Parcels B, C, and E will be evaluated, and if appropriate, cleaning, or relining, or encapsulation, or other appropriate technologies will be considered for inclusion in the remedial action for each respective parcel.

Comment

6) Section 2.3. p. 2-4, paragraph 3. Please estimate the length of lines that could not be cleaned and explain whether it was possible to video these sections to assess the amount of sediment that could not be removed. If possible, estimate the volume of sediment that was not removed. This information about inaccessible lengths is not included in most of the basin specific discussions (e.g., all of the basins except Basins I and III lack the lengths of inaccessible lines).

Response

The response to General comment #1 above indicates the length of line that could not be cleaned. Lines left uncleaned were due either to the line being submerged as a result of Bay influence or a discontinuity in the line that would not permit access by the video or cleaning equipment. In either instance it was not possible to video these line segments to determine the volume of sediment that remains in the line.

Comment

7) Section 2.3, p. 2-4, last paragraph and Appendix B. Please clarify how the segments that could not be cleaned were identified in the Appendix B tables. These segments should not be labeled "Pass" in the remarks column; some method of identifying inaccessibility should clearly indicate that fact that sediments remain in these segments because they could not be cleaned.

Response

Further detail has been added to the revised Appendix B Tables to identify segments which could not be cleaned due to inaccessibility. The cleaning criteria are discussed in detail in paragraph 4 of the Introduction section to the Summary Report.

Comment

8) Page 2-5, section 2.4, first paragraph, last sentence. Any conclusions about threat or absence of? Are sediments likely at steady state due to being submerged?

Response

No conclusions were drawn in the report regarding sediments remaining in the submerged sections relative to potential threats they may pose to the environment. Due to the period of time the sediments are likely to have been in the submerged lines it is likely that this material has reached a steady state condition.

Comment

9) Page 2-5, fourth paragraph. See comment 2 above,

Response

See response to Specific comment 2 above.

Comment

10) Section 2.4, p. 2-5, paragraph 4. The last sentence of the paragraph, where a vault with no sediment trap is classified as a catch basin is confusing. On page 1-3, the second sentence in the second paragraph states that the difference between a catch basin and a manhole is "that a catch basin has a sediment trap in the bottom while a manhole does not." Please explain why these vaults were classified as catch basins.

Response

See response to Specific comment 2 above.

Comment

11) Section 2.4, p. 2-5, last paragraph and Appendix C. The first paragraph in this section describes several cases where several catch basins/manholes could not be cleaned, but the tables in Appendix C only include two locations that were not cleaned. Please explain whether all locations that could not be cleaned were included in Appendix C.

Also, the locations that could not be cleaned should not be labeled "Pass" unless it was possible to verify that there was no sediment in the catch basin/manhole after cleaning was completed.

Response

The text in Section 2.4 has been changed to accurately reflect the data shown in Appendix C. Please refer again to the cleaning criteria, as referenced in response to #7 above. Additional notation has been added to Appendix C to clarify instances where cleaning criteria were met and all known locations are included.

Comment

12) The report should discuss the RCRA compliance issues. For example in section 2.6. Explain why the method of sediment handling was changed mid-project.

Response

The method of handling the material removed from the storm drain lines as identified in the Work Plan was called into question by the EPA after the field activities had started. Although we are not in agreement with the EPA interpretation, the method used to store the material removed from the storm drain lines was changed and subsequent to those discussions material was temporarily stored in roll-off bins prior to disposal.

Comment

13) Page 2-6. EPA is pleased to see that the Navy used Chem Waste landfill in Kettleman Hills, CA which is approved to receive CERCLA waste per the RCRA offsite rule.

Response

Comment is acknowledge.

Comment

14) Section 2.6, page 2-6. Please discuss how the sediments were segregated to allow the different waste classifications to be determined.

Response

Waste material was not segregated. Please refer to the response to General comment #2 above.

Comment

15) Appendix E - Tables. Please add regulatory level used to screen the hits and to characterize for the sediment stockpiles for disposal.

Response

Analysis results shown in Appendix E were from samples taken at each temporary storage location. These results were provided to the licensed disposal facilities. Each facility is licensed to permit acceptance of material subject to criteria specific to that location. On the basis of those acceptance criteria the disposal facility made a determination as to whether the material in each temporary storage location would be accepted for disposal and what specific treatment, if any, would be required as part of the acceptance requirements. Generally, if analysis results indicate that the material has concentrations below RCRA levels it may be accepted at a licensed Class 2 facility, subject to additional testing requirements that may be required by that facility. Material

with concentrations at or above RCRA levels will require disposal at a Class 1 facility. Non-contaminated construction debris may be disposed at Class 3 landfills.

Comment

16) Section 2.7 and Section 2.9, p. 2-7. Neither of these two sections include a discussion of the disposal or cleaning of the contaminated sediment stockpile HDPE liners. Please discuss the final handling of these materials.

Response

All temporary storage material (liner material and hay bales) was loaded and sent for disposal with the material that was stored in that storage cell.

Comment

17) Page 3-1, section 3.0. See comment 5 above.

Response

See response to Comment #5 above.

Comment

18) Section 3.0. Please elaborate on "inaccessible laterals."

Response

Laterals were inaccessible for cleaning due to several reasons. The line cleaning equipment required access to a downstream catch basin or manhole to clean a line segment. The cleaning device was propelled up the line and the rinsate water with the removed material flowed down to be removed at the catch basin or manhole where the equipment was located. In order to clean a lateral a catch basin or manhole would have had to be located at the point of intersection of the lateral with the main line. This was generally not the case. Furthermore, many of the lateral lines were constructed of pipe whose diameter was too small to allow use of the cleaning equipment utilized on this job. The only access points to these laterals were also in many cases within buildings which prohibited the cleaning equipment from gaining access to these laterals.

Comment

19) Page 3-2, section 3.2. Was any portion of the rubber like deposits removed and sampled? Similar material was found in dry dock 4 and tests with deionized water found that copper and other metals harmful to the bay could leach right out of it. Is there any other way to clean, or encapsulate if confirmed to pose a bay threat?

Response

The lines at Dry dock 4 were cleaned using the same high pressure cleaning equipment that was used in the storm drain systems elsewhere at Hunters Point. Where accessibility was possible hand removal techniques were also used at Dry dock 4 when the high pressure cleaning equipment did not remove sediments. For the most part it was not possible to use hand removal techniques in the storm drain lines due to the size of the lines and accessibility constraints. As a result, the rubber like deposits within the storm drain lines were neither removed nor sampled. If

this material is confirmed as a potential threat there may be a way to encapsulate or remove the storm drain pipe.

Comment

20) Page 3-2, section 3.3. See comment 13 above,

Response

It is assumed that the reference to "comment 13" is a typographical error and should read "comment 18". The response regarding "inaccessible laterals" is the same as the previous response given for Comment 18 above.

Comment

21) Section 3.2, p. 3-2, paragraph 2, sentence 3. It was noted that during cleanup of the Basin II area, hard, "rubber type" black deposits, resistant to cleaning were found in one manhole, three catch basins, and one lateral line. Please discuss whether any further characterization was done to determine the composition of the deposits and whether it would be necessary to remove this material in the future.

Response

Please refer to the response to Comment 7 and the cleaning criteria discussed in the Introduction to the Summary Report. As stated in the cleaning criteria, if a deposit could not be removed without risking damage to the pipe it was to be left in place. This was the case with regard to the black deposits that remained within the structures identified in this comment. There was no further characterization done of this material.

Comment

22) Section 3.4, p. 3-3, paragraph 1, sentence 2. See comment number 7 concerning the characterization of hard, "rubber type" black deposits left in the storm drain line and clarify whether this material was characterized.

Response

See response to Comment 21 above.

Comment

23) Figures are outstanding

Response

Comment is acknowledged.

CALIFORNIA EPA / S.F BAY REGIONAL QUALITY CONTROL BOARD COMMENTS

Comment

1) The text of Section 1.1 notes 99,000 linear feet of line in Parcels B, C, D, and E, while the total length of line in the 10 basins described in Section 3 is 107,000 linear feet.

Response

The 99,000 linear feet figure is correct. The 107,000 linear foot figure was an estimate only.

Comment

2) The text of Section 1.1 notes 945 catch basins/manholes in the storm drain system. The total number of catch basins/manholes cleaned as summarized in Section 3 is 647. The balance between these two numbers should be accounted for among areas outside this program (Parcel A), areas not cleaned because of access or submersion problems, and catch basins/manholes inspected but not cleaned.

Response

See response to General Comment #1 of the EPA above. Further clarification has been provided in both revised Appendix B and C to the Summary Report. The total number of catch basins and manholes cleaned is 669. The total number of catch basins and manholes not cleaned is 74. The difference between the total number of catch basins and manholes cleaned and not cleaned, 743 and 945 total estimated as identified in Section 1.1 is accounted for in the area outside this program, Area A.

Comment

3) Comparison of the cleaning logs in Appendix C to the figures in Section 3 showed generally good agreement. Some minor discrepancies were noted. For example, in Basin VII, MH A11, CB A10-1, CB C11, and CB C11-1 are shown on Figure 3-7 as cleaned, but are not included in Table C-7

Response

The cleaning records for catch basins and manholes of Basins I through X are presented in revised Tables C-1 through C-10, correspondingly. These tables superseded the previous version and should eliminate the discrepancies as stated in Comment 3.

Final Comment


In Appendix D, it would be useful to summarize the waste concentration values used in making decisions regarding waste classification and disposition. Also, please provide information regarding the reporting limits below which concentrations are reported as nondetectable.


Response


Attachment 1.0 to the Sampling and Analysis Plan for the Storm Drain removal Action contains the Requirements for Batch Wastewater Discharges, issued by the City and County of San Francisco. A copy of this document is attached as reference. The Batch Wastewater discharge


permits were issued by the City and County of San Francisco after wastewater laboratory analyses submitted to them were reviewed and compared to those requirements.


Also attached is a copy of one of the wastewater laboratory analysis results which indicate the reporting limits for each constituent analyzed. The same reporting limits were used for the analyses that were run on each wastewater sample.
































Fig. 16-1. A brick manhole.




Fig. 16-9. Types of catch basins. (a) Combined gutter and curb inlet. (b) Gutter inlet only. Construction as recommended by Clay Products Association.

5090 Ser 1832.2/L7042 25 Nov 1996

Mr. Cyrus Shabahari
California Department of Toxic Substances Control
Site Mitigation Branch
700 Heinz Avenue, Building F
Berkeley, CA 94710

Dear Mr. Shabahari.

The purpose of this letter is to confirm our phone conversation with you on November 19, 1996, during which we discussed the IR-50 Storm Drain System Removal Action at the Hunters Point Shipyard (HPS) in San Francisco, California. This removal action is designed to eliminate the potential for migration of contaminated sediments into the San Francisco Bay via the HPS storm drain system by cleaning sediments from the storm drain system and disposing of the sediments off site.

As part of the sediment removal process, storm drain lines will be sprayed with a high-pressure jet washer, while the downstream manhole is plugged to contain wash water and sediments. The resulting sediment slurry will be collected in specially adapted roll-off containers equipped with filters and decanting equipment. The decanted water will be used whenever possible for additional line cleaning. Spent wash water will be characterized before discharge to the local publicly owned treatment works. All sediments will be characterized as hazardous or nonhazardous, and the results of the characterization will dictate the subsequent management practices for sediments in each container.

As we discussed during our phone conversation, we have included with this letter (enclosure (1)) eight pages from the Storm Drain System Removal Action Work Plan, which was prepared by IT Corporation for the Navy. These pages will provide some details of how the on-site filtration system is being used for phase separation. We have also included a list of references (enclosure (2)) to the filtering system and the phase separation process, which are in the Action Memorandum and in the Engineering Evaluation/Cost Analysis for the IR-50 Storm Drain System Removal Action at the Hunters Point Shipyard.

If you have any questions regarding this letter, please contact either myself at (415) 244-2655, or Mr. William Radzevich at (415) 244-2555.

Sincerely yours,

RICHARD E. POWELL
Lead Remedial Program Manager for HPS/TI
By direction of
the Commander

5090 Ser 1832.2/L7042 25 Nov 1996

Enclosures:

(1) Eight pages from the Storm Drain System Removal Action Work Plan

(2) List of References from Action Memorandum and Engineering Evaluation/Cost Analysis for the IR-50 Storm Drain System Removal Action at HPS

Copies to:

U.S. Environmental Protection Agency (Attn: Shery Lauth)

Regional Water Quality Control Board (Attn: Mr. Richard C. Hiett)

PRC Environmental Management (Attn: Mr. James Sickles)

Blind copies to:

62.3, 62C, CSO-HPS(ES), 1832, 1832.2, 09CMN

Chron, Green

Activity File: HPA (File: L67042WR) ab

reau of Environmental Regulation and Management

Rayview Flass 3801 Third St. Suins 600 San Francisco, CA 94124

April 11, 1994

REQUIREMENTS FOR BATCH WASTEWATER DISCHARGES

The information that must be included in applications for permits to carry out batch discharges of wastewater into the City and County of San Francisco's (City's) sewerage system is outlined below.

Such batch discharges may result from de-watering of construction sites, wells drilled to investigate/mitigate a suspected contaminated site, water used for cleaning/hydrostatic testing of pipes or tanks, or any other activity which generates wastewater, other than from routine commercial/industrial processes.

The discharges shall be subject to payment of sewer service charges in accordance with he provisions of applicable City laws.

The application for discharge shall be submitted no later than 45 days prior to the prop: ied commencement of the discharge and must include the following information:

- (1) The source (i.e. the activity and location at which the wastewater is generated):
- (2) The total estimated volume of proposed discharge;

(3) The proposed discharge location (including location of side sewer, street manhole(s) or storm drain(s) proposed for disposal use); and,

(4) A copy of applicable analytical results (see below) from a representative sample (i.e. a sample portion of the wastewater that is as nearly identical in content and consistency as possible to that in the larger body of wastewater being sampled).

INOTE: All sampling and analysis shall be performed in accordance with techniques and procedures approved by the U.S. Environmental Protection Agency (EPA) and amendments thereto, or otherwise approved by the El'A.

These procedures must be performed by a laboratory approved to do so l.y the Environmental Laboratory Accreditation Program (ELAP), State of California, Department of Health Services, Berkeley, California. ELAP can be read at (510) 540-2800.]

The following applicable analytical results, as indicated in Table 1A below, are require i from all wastewaters from all sources.

Table 1A. General Analytical Requirements For Batch Wastewater Discharges
- ALL Sources

Pollutant/Pollutant Property	Analytical Methodology / Test Methods2	Limit ³ (mg/L)
pH (pH units)	4500-H+ / 9040	6.0 min.; 9.5 max.
Dissolved sulfides	4500-S1- / 9030A	0.5
Hydrocarbon Oil and Grease	5520F /	100
Total Recoverable Oil and Grease	5520B / 9070	300
Total suspended solids	2540D /	
Chemical oxygen demand	5220 /	

Standards Methods For The Examination Of Water And Wastewater, Greenberg, Arnold B., et al., American Public Health Association, et al., Washington, D.C., 1992, 18th ed., as amended;

[&]quot;Test Memods Por Evaluating Solid waste, U.S. Environmental Protection Agency, November 1986 (Rev. July 1992), 3rd ed., SW-846, as amended.

³ Chapter X (Public Works Code) of Part II of the San Francisco Municipal Code, Article 4.1, Section 123.

Table 1A. (Cont'd)

Cyanide (Total)	4500-CN- D,B / 9010A, 9012	1.0
Pienois	5530D /	23.0
Zinc (Total)	3500-Zn A,B,C / 6010A, 7950, 7951	7.0
Silver (Total)	3500-Ag A,B,C / 6010A, 7760A, 7761	0.6
Nickel (Total)	3500-Ni A,B,C / 6010A, 7520	2.0
Mercury (Total)	3500-Hg A,B / 7470	0.05
Lead (Total)	3500-РЬ А,В,С / 6010А, 7420, 7421	1.5
Copper (Total)	3500-Cu A,B,C / 6010A, 7210, 7211	4.0
Chromium (Total)	3500-Ct A,B,C / 6010A, 7190, 7191	5.0
Cadmium (Total)	3500-Cd A,B,C / 6010A, 7130, 7131	0.5
Arsenic (Tetal)	3113, 3114, 3120 / 7060, 7061A	4.0
Pollutant/Pollutant Property	Analytical Methodology / Test Methods	Limić (mg/L)

⁴ City and County of San Francisco, Department of Public Works, Order No. 158170.

In addition to the analyses listed in Table 1A, above, wastewaters that are suspected of petroleum contamination because of location and site history (e.g. service stations, garages, automotive repair/wrecking areas, fuel oil storage areas, etc.) OR wastewaters that are suspected of contamination from hazardous waste sites are also subject to the specified analyses, as delineated in Table 1B.

NOTE: All III areas of the City and County of San Francisco are suspected of hazardous waste contamination. Therefore permit applications for wastewater discharges from such locations also require the submittal of the specified analyses, as delineated in Table 1B.

For each "Pollutant/Pollutant Parameter" or "Contaminant" or "Substance" listed in the tables, the most stringent "Limit" or "Regulatory Level" or "Soluble/Total Threshold Limit Concentration" must be satisfied.

Applications for permits to perform batch wastewater discharges should be addressed as follows:

Mr. Tommy Lee
Section Engineer
City and County of San Francisco
Department of Public Works
Bureau of Environmental Regulation
and Management
Bayview Plaza
3801 - 3rd Street, Suite 600
San Francisco, CA 94124

If you have any questions or wish further explanation, you may call Tommy Lee at (415) 695-7321.

Table 1B. Additional Analytical Requirements For Batch Wastewater Discharges
- Sources Suspected of Petroleum or Hazardous Waste Contamination

Contaminant	Analytical Test Methods!	Regulatory Level* (mg/L)
Plashpoint (*C, *F)	1010	\$ 60°C (140°F)
Benzene	8020	0.\$
Carbon Tetrachloride	8010, \$240	0.5
Chlordane	8250 or 8270	0.03
Chlorobenzene	E020, 8240	100.0
Chloroform	8010, 8240	6.0
o-Cresol	8250 or 8270	200.0
m-Cresol	8250 or 8270	200.0
p-Cresol	8250 or 8270	200.0
Cresol	8250 or 8270	200.0

² Water Por Pratricting Solid Water, U.S. Environmental Protection Agency, November 1986 (Rev. July 1992), 3rd ed., SW-846, as amended.

⁴ Title 22, California Code of Regulations, Section 66261.24(a)(1)(B).

Table 1B. (Cont'd)

Contaminant	Analytical Test Methods	Regulatory Level (mg/L)
2,4-D	8250 or 8270	10.0
1,4-Dichlorobenzene	8010, 8250 or 8270	7.5
1,2-Dichloroethane	8010, 8240	0.5
1,1-Dichloroethylene	8010, 8240	0.7
2,4-Dinitrotoluene	8250 or 8270	0.13
Endrin	8250 or 8270	0.02
Heptachlor (and its epoxide)	8250 or \$270	0.008
Hexachlorobenzene	8250 or 8270	0.13
Hexachlorobutadiene	8250 or 8270	0.5
Hexachloroethane	8010, 8 240	3.0
Lindane	8250 or 8270	0.4
Methoxychlor ·	8250 or 8270	10.0
Methyl ethyl ketone	8240	200.0

Table 1B. (Cont'd)

Contaminant	Analytical Test Methods	Regulatory Level (mg/L)
Nitrobenzene	8250 or 8270	2.0
Pentachlorophenol	8250 or 8270	100.0
Pyriding	8250 or 8 270	5.0
Selenium	6010A, 7740, 77 41	1.0
Tetrachloroethylene	B010, 8240	0.7
Тохарінене	8250 or 8270	0.5
Trichloroethylene	8010, 8240	0.5
2,4,5-Trichlorophenol	8250 or 8270	400.0
2,4,6-Trichlorophenol	8250 or 8270	2.0
2,4,5-TP (Silvex)	8250 or 8270	1.0
Vinyl chloride	8010, 8240	0.2

Table 1B. (Cont'd)

Substance	Analytical Test Methods	STLC	TTLC ¹ Wet-Weight
		(mg/L)	(mg/kg)
Antimosy and/or antimony compounds	6010A, 70 40, 7041	15	500
Arsenic and/or arsenic compounds	6010A, 7060, 7061	5.0	500
Asbestos	40 CFR Part 763°	## * =	1.0 (as percent)
Barium and/or barium compounds (excluding barite)	6010A, 7080, 7081	100	10,000 ^{te}
Beryllium and/or beryllium compounds	6010A, 7090, 7091	0.75	75
Cadmium and/or cadmium compounds	6010A, 7130, 7131	1.0	100
Chromium (VI) compounds	7198, 7195, 7196, 7197	5	500
Chromium and/or chromium (III) compounds	6010A, 7190, 7191	5	2,500

⁷ Soluble Threshold Limit Concentration. Title 22, California Code of Regulations, Section 66261.24(a)(2)(A).

⁴ Total Thresheld Limit Concentration. Title 22, California Code of Regulations, Section 66261.24(a)(2)(A).

Interim Method for the Determination of Asbestos in Bulk Insulation Samples, 40 CFR Part 763, Subpart P, Appendix A.

¹⁰ Excluding barlum sulfate.

Table 1B. (Cont'd)

Substance	Analytical Test Methods	STIC	TTLC Wet-Weight
		(mg/L)	(mg/kg)
Cobalt and/or cobalt compounds	6010A	80	8,000
Copper and/or copper compounds	6010A, 7210 , 7211	25	2,500
Pluoride salts	300.0, 340.1, 340.2, 340.3 ¹¹	180	18,000
Lead and/or lead compounds	6010A, 7420 , 7471	5.0	1,000
Mercury and/or mercury compounds	7470, 7471	0.2	20
Molybdenum and/or molybdenum compounds	6010A	350	3,500
Nickel and/or nickel compounds	6010A, 7520, 7521	20	2,000
Selenium and/or selenium compounds	6010A, 7740, 7741	1.0	100
Silver and/or silver compounds	6010A, 7760, 7761	5	500
Thallium and/or thallium compounds	6010A, 7840, 7841	7.0	700
Vanadium and/or vanadium compounds	6010A, 7910, 7911	24	2,400
Zinc and/or zinc compounds	6010A, 7950, 7951	250	5,000

¹¹ Methods for Chemical Analysis of Water and Wastes, EPA-600/4-79-020, U.S. Environmental Protection Agency, 1979.

Table 1B. (Cont'd)

Substance	Analytical Test Methods	SILC12	TILC
		(mg/L)	Wet-Weight (mg/kg)
Aldrin	8080, 8250 or 8270	0.14	1.4
Chlordane	8080, 8250 or 8270	0.25	2.5
DDT, DDB, DDD	8080, 8250 or 8270	0,1	1.0
2,4-Dicklorophenoxyacetic acid	8150	10	100
Dieldrin	8080, 8250 or 8270	0.8	8.0
Dioxin (2,3,7,8-TCDD)	8280	0.001	0.01
Endrin	8080, 8250 or 8270	0.02	0.2
Heptachlor	8080, 8250 or 8270	0.47	4.7
Kepone	Section 5, A, (5), (a)13	2.1	21

¹² Title 22, California Code of Reguments, Section 66261.24(a)(2)(B).

¹³ Manual of Analytical Methods for the Analysis of Pesticides in Humans and Environmental Samples, EPA-600/8-80-038, U.S. Environmental Protection Agency, 1980.


Table 1B. (Cont'd)


Substance	Analytical Test Methods	STIC	TTLC Weight
		(mg/L)	(mg/kg)
Lead compounds, organic	Appendix XI ¹⁴	~**	13
Lindane	8080, 8250 or 8 270	0.4	4.0
Methoxychlor	8080, 8250 or 8270	10	100
Mirex	8080, 8250 or 8270	2.1	21
Pentachlorophenol	8040, 8250 or 8270	1.7	17
Polychlorinated biphenyls (PCBs)	8080, 8250 or 8270	5.0	50
Toxaphene	8080, 8250 or 8270	0.5	5
Trichloroethylene	8010, 82 40	204	2,040
2,4,5-Trichlorophenoxypropionic acid	8150	1.0	10

¹⁴ Title 22, California Code of Regulations, Section 66261.126, Appendix XI.

BATCH WASTEWATER DISCHARGES

Required Analytical Results






BATCH WASTEWATER PERMIT APPLICATION

1.	Name of business generating wastewater:
2.	Mailing address of business generating wastewater:
3.	Activity resulting in wastewater generation:
4.	Location of wastewater generation :
5.	Total estimated volume (or volume flow rate) of wastewater discharge :
6.	Estimated duration of wastewater discharge:
7.	Proposed sewer opening for discharge: Side Sewer: Street Sewer: Catch Basin: Manhole
8.	Location of sewer opening:

	Will the wastewater be subjected to any treatment before discharge ?						
	□ YES; □ NO						
•	If so, describe the method(s) of treatment:						
•	Attach a copy of applicable analytical results from a representative sample of the wastewater. (See Tables 1A & 1B in "Requirements For Batch Wastewater Discharges")						
	Certification Statement :						
	I certify under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.						
	Name: Tide:						

¹ To be signed by an authorized representative of the discharger. An authorized representative may be (a) a principal executive officer or official; (b) a general partner or proprietor; or (c) a duly authorized representative of the individual designated in (a) or (b).



92-107

80-121

Volatile Organics by GC/MS IT Corporation Client: Analysis Method: EPA 8260 Project#: 767631 Prep Method: EPA 5030 Location: Hunters Point Field ID: 61WW08 Sampled: 09/12/97 Lab ID: 130610-001 Received: 09/12/97 Matrix: Water Extracted: 09/12/97 Batch#: 36240 Analyzed: 09/12/97 Units: ug/L Diln Fac: 1 Analyte Result Reporting Limit Chloromethane ND 10 Bromomethane ND 10 Vinyl Chloride ND 10 Chloroethane ND 10 Methylene Chloride ND 20 Acetone ND 20 Carbon Disulfide ND 5.0 Trichlorofluoromethane ND 5.0 1,1-Dichloroethene ND 5.0 1,1-Dichloroethane ND 5.0 trans-1,2-Dichloroethene ND 5.0 cis-1,2-Dichloroethene 4.1 J 5.0 Chloroform ND 5.0 Freon 113 ND 5.0 1,2-Dichloroethane ND 5.0 2-Butanone ND 10 1,1,1-Trichloroethane ND 5.0 Carbon Tetrachloride ND 5.0 Vinyl Acetate ND 50 Bromodichloromethane ND 5.0 1,2-Dichloropropane ND 5.0 cis-1,3-Dichloropropene ND 5.0 Trichloroethene 3.7 J 5.0 Dibromochloromethane ND 5.0 1,1,2-Trichloroethane ND 5.0 Benzene ND 5.0 trans-1,3-Dichloropropene ND 5.0 Bromoform ND 5.0 2-Hexanone ND 10 4-Methyl-2-Pentanone ND 10 1,1,2,2-Tetrachloroethane ND 5.0 Tetrachloroethene ND 5.0 Toluene ND 5.0 Chlorobenzene ND 5.0 Ethylbenzene ND 5.0 Styrene ND 5.0 m,p-Xylenes 5.0 MD o-Xylene ND 5.0 Surrogate *Recovery Recovery Limits 1,2-Dichloroethane-d4 108 87-121

100

104

Bromofluorobenzene

Toluene-d8



Semivolatile Organics by GC/MS

Client: IT Corporation Analysis Method: EPA 8270B

Project#: 767631 Prep Method: EPA 3520

Location: Hunters Point

 Field ID:
 61WW08
 Sampled:
 09/12/97

 Lab ID:
 130610-001
 Received:
 09/12/97

 Matrix:
 Water
 Extracted:
 09/15/97

Matrix: Water Extracted: 09/15/97
Batch#: 36293 Analyzed: 09/16/97

Units: ug/L Diln Fac: 1

Analyte	Result	Reporting Limit
Phenol	ND	9.4
2-Chlorophenol	ND	9.4
Benzyl alcohol	ND	9.4
2-Methylphenol	ND	9.4
3,4-Methylphenol	ND	9.4
2-Nitrophenol	ND	47
2,4-Dimethylphenol	ND	9.4
Benzoic acid	ND	47
2,4-Dichlorophenol	ND	9.4
4-Chloro-3-methylphenol	ND	9.4
2,4,6-Trichlorophenol	ND	9.4
2,4,5-Trichlorophenol	ND	47
2,4-Dinitrophenol	ND	47
4-Nitrophenol	ND	47
4,6-Dinitro-2-methylphenol	ND	47
Pentachlorophenol	ND	9.4
N-Nitrosodimethylamine	ND	9.4
Aniline	ND	9.4
bis(2-Chloroethyl)ether	ND	9.4
1,3-Dichlorobenzene	ND	9.4
1,4-Dichlorobenzene	ND	9.4
1,2-Dichlorobenzene	ND	9.4
bis(2-Chloroisopropyl) ether	ND	9.4
N-Nitroso-di-n-propylamine	ND	9.4
Hexachloroethane	ND	9.4
Nitrobenzene	ND	9.4
Isophorone	ND	9.4
bis(2-Chloroethoxy)methane	ND	9.4
1,2,4-Trichlorobenzene	ND	9.4
Naphthalene	ND	9.4
4-Chloroaniline	ND	9.4
Hexachlorobutadiene	ND	9.4
2-Methylnaphthalene	ND	9.4
Hexachlorocyclopentadiene	ND	47
2-Chloronaphthalene	ND	9.4
2-Nitroaniline	ND	47
Dimethylphthalate	ND	9.4
Acenaphthylene	ND	9.4

	Semivolatile Orga	nics by GC/MS
Field ID: 61WW08		Sampled: 09/12/97
Lab ID: 130610-001		Received: 09/12/97
Matrix: Water		Extracted: 09/15/97
Batch#: 36293		Analyzed: 09/16/97
Units: ug/L		-
Diln Fac: 1		
Analyte	Result	Reporting Limit
2,6-Dinitrotoluene	ND	9.4
3-Nitroaniline	ND	47
Acenaphthene	ND	9.4
Dibenzofuran	ND	9.4
2,4-Dinitrotoluene	ND	9.4
Diethylphthalate	ND	9.4
4-Chlorophenyl-phenylether	ND	9.4
Fluorene	ND	9.4
4-Nitroaniline	ND	47
N-Nitrosodiphenylamine	ND	9.4
Azobenzene	ND	9.4
4-Bromophenyl-phenylether	ND	9.4
Hexachlorobenzene	ND	9.4
Phenanthrene	ND	9.4
Anthracene	ND	9.4
Di-n-butylphthalate	ND	9.4
Fluoranthene	ND	9.4
Pyrene	ND	9.4
Butylbenzylphthalate	ND	9.4
3,3'-Dichlorobenzidine	ND	47
Benzo(a)anthracene	ND	9.4
Chrysene	ND	9.4
bis(2-Ethylhexyl)phthalate	ND	9.4
Di-n-octylphthalate	ND	9.4
Benzo(b) fluoranthene	ND	9.4
Benzo(k) fluoranthene	ND	9.4
Benzo(a)pyrene	ИD	9.4
Indeno(1,2,3-cd)pyrene	ND	9.4
Dibenz (a, h) anthracene	ND	9.4
Benzo(g,h,i)perylene	ND	9.4
Surrogate	%Recovery	Recovery Limits
2-Fluorophenol	73	21-110
Phenol-d5	75 75	10-110
2,4,6-Tribromophenol	82	10-110
Nitrobenzene-d5	77	35-114
2-Fluorobiphenyl	76	43-116
Terphenyl-d14	56	33-141
		33-141



Organochlorine Pesticides and PCBs

Client: IT Corporation Analysis Method: EPA 8080 Project#: 767631 Prep Method: EPA 3520

Location: Hunters Point

| Field ID: 61WW08 | Sampled: 09/12/97 | Lab ID: 130610-001 | Received: 09/12/97

 Lab ID:
 130610-001
 Received:
 09/12/97

 Matrix:
 Water
 Extracted:
 09/12/97

 Batch#:
 36252
 Analyzed:
 09/17/97

Units: ug/L Diln Fac: 1

analyte	Result	Reporting Limit
lpha-BHC	ND	0.047
eta-BHC	ND	0.047
amma-BHC	ND	0.047
elta-BHC	ND	0.047
eptachlor	ND	0.047
ldrin	ND	0.047
eptachlor epoxide B	ND	0.047
eptachlor epoxide A	ND	0.047
ndosulfan I	ND	0.047
Dieldrin	ND	0.094
.,4'-DDE	ND	0.094
Endrin	ND	0.094
Indosulfan II	ND	0.094
ndosulfan sulfate	ND	0.094
,4'-DDD	ND	0.094
ndrin aldehyde	ND	0.094
4'-DDT	ND	0.094
Ihlordane	ND	0.47
Methoxychlor	ND	0.47
oxaphene	ND	0.94
lirex	ND	0.94
Kepone	ND	0.94
roclor-1016	ND	0.47
aroclor-1221	ND	0.94
Aroclor-1232	ND	0.47
aroclor-1242	ND	0.47
Aroclor-1248	ND	0.47
Aroclor-1254	ND	0.47
roclor-1260	ND	0.47
urrogate	%Recovery	Recovery Limits
CCMX	76	60-140
Decachlorobiphenyl	40*	60-140

^{*} Values outside of QC limits

SAMPLE ID: 61WW08 LAB ID: 130610-001

CLIENT: IT Corporation

PROJECT ID: 767631

LOCATION: Hunters Point

MATRIX: Water

Curtis & Tompkins. Ltd.

DATE SAMPLED: 09/12/97

DATE RECEIVED: 09/12/97

DATE REPORTED: 09/16/97

California TITLE 26 Metals

Compound	Result (ug/L)	Reporting Limit (ug/L)	IDF	QC Batch	Method	Analysis Date
Antimony	70	60	1	36287	EPA 6010A	1 ' '
Arsenic	ND	5.0	1	36287	EPA 6010A	, , ,
Barium Beryllium	220 ND	10 2.0	1	36287 36287	EPA 6010A EPA 6010A	, ,
Cadmium	ND	5.0	1	36287	EPA 6010A	
Chromium (total)	ND	10	1	36287	EPA 6010A	
Cobalt	ND	20	1	36287	EPA 6010A	1 ' '
Copper	93	10	1	36287	EPA 6010A	
Lead	8.9	3.0	1	36287	EPA 6010A	09/16/97
Mercury	0.26	0.20	1	36270	EPA 7470	09/15/97
Molybdenum	640	20	1	36287	EPA 6010A	1 ''
Nickel	44	20	1	36287	EPA 6010A	
Selenium	ND	5.0	1	36287	EPA 6010A	- / - / -
Silver	ND	5.0	1	36287	EPA 6010A	,
Thallium	ND	5.0	1	36287	EPA 6010A	. , ,
Vanadium	ND	10	1	36287	EPA 6010A	1 ' '
Zinc	180	20	1	36287	EPA 6010A	09/16/97
				L	<u> </u>	

ND = Not detected at or above reporting limit



Client: IT Corporation

Laboratory Login Number: 130610

Project Name: Hunters Point

Project Number: 767631

Report Date: 16 September 97

ANALYSIS: Total Oil & Grease (Gravimetric) METHOD: SMWW 17:5520B

Lab ID		Matrix	Sampled	Received	Analyzed		Units	RL	Analyst	QC Batch
130610-001	61 WWAS	Water	12-SEP-97	12-SEP-97	16-SEP-97	ND	mg/L	5	SDG	36319
130010 001	01W00						J, _			
:										

ND = Not Detected at or above Reporting Limit (RL).



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97 DATE RECEIVED: 09/12/97 DATE ANALYZED: 09/16/97

BATCH#: 36307

ANALYSIS: CHEMICAL OXYGEN DEMAND

ANALYSIS METHOD: EPA 410.4

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61WW08	40	mg/L	10
METHOD BLANK	N/A	ND	mg/L	10

ND = Not detected at or above reporting limit.

QA/QC SUMMARY:	LCS,	MS/MSD	OF	SAMPLE	130578-002		
============	=====	======	===	======	:============	=======================================	
LCS REC, %						98	
MS/MSD REC, %						87	
RPD, %						5	



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97 DATE RECEIVED: 09/12/97 DATE ANALYZED: 09/15/97

BATCH#: 36298

ANALYSIS: CYANIDE

ANALYSIS METHOD: EPA 335.2

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61WW08	ND	ug/L	10
METHOD BLANK	N/A	ND	ug/L	10

ND = Not detected at or above reporting limit.

QA/QC SUMMARY:	BLANK SPIKE	AND BLAN	K SPIKE	DUPLICATE				
=======================================		=======	======	=======================================				
REC, %				93				
RPD, %				2				



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97 DATE RECEIVED: 09/12/97 DATE ANALYZED: 09/16/97

BATCH#: 36303

ANALYSIS: FLASH POINT

ANALYSIS METHOD: EPA 1010

LAB ID SAMPLE ID RESULT UNITS

130610-001 61WW08 >150 F

ND = Not detected at or above reporting limit.

QA/QC SUMMARY: SAMPLE DUPLICATE OF 130610-001

RPD, %



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97
DATE RECEIVED: 09/12/97

DATE ANALYZED: 09/15/97 BATCH#: 36294

ANALYSIS: FLUORIDE

ANALYSIS METHOD: EPA 340.2

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61 W W08	1.2	mg/L	0.25
METHOD BLANK	N/A	ND	mg/L	0.25

ND = Not detected at or above reporting limit.



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97
DATE RECEIVED: 09/12/97
DATE ANALYZED: 09/15/97

BATCH#: 36275

ANALYSIS: PHENOLIC COMPOUNDS ANALYSIS METHOD: EPA 420.1

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61WW08	ND	ug/L	50
METHOD BLANK	N/A	ND	ug/L	50

ND = Not detected at or above reporting limit.



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97 DATE RECEIVED: 09/12/97 DATE ANALYZED: 09/15/97

BATCH#: 36286

ANALYSIS: DISSOLVED SULFIDE ANALYSIS METHOD: EPA 376.2

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61WW08	ND	mg/L	0.04
METHOD BLANK	N/A	ND	mg/L	0.04

ND = Not detected at or above reporting limit.

QA/QC SUMMARY:	LCS, MS/MSD OF	SAMPLE 130578-002	
			============
LCS REC, %			97
MS/MSD REC, %			99
RPD, %			1
=======================================			



PROJECT#: 767631

LOCATION: HUNTERS POINT

DATE SAMPLED: 09/12/97 DATE RECEIVED: 09/12/97 DATE ANALYZED: 09/15/97

BATCH#: 36292

ANALYSIS: TOTAL SUSPENDED SOLIDS

ANALYSIS METHOD: EPA 160.2

LAB ID	SAMPLE ID	RESULT	UNITS	REPORTING LIMIT
130610-001	61WW08	ND	mg/L	5
METHOD BLANK	N/A	ND	mg/L	5

ND = Not detected at or above reporting limit.

QA/QC SUMMARY: SAMPLE DUPLICATE OF 130610-001

2.4 Catch Basin/Manhole Cleaning

Each catch basin/manhole was inspected during the project. Any catch basin/manhole which was found to contain sediment, debris or liquids, or which required cleaning was cleaned (Appendix A, Photo 9). A few catch basins/manholes which were located in hard-to-reach places were cleaned using a flex hose extension on the vactor truck. A catch basin in Basin II was located under a permanent office trailer and could not be inspected or cleaned. A catch basin which appeared to have been taken out of service, was found backfilled with concrete and therefore not cleaned. Catch basins/manholes which were adjacent to outfall pipes or discharged directly in the Bay also could not be cleaned.

During the removal action, it was discovered that some catch basins/manholes had become buried over the years under soil or pavement. In order to locate these catch basins/manholes, a special locating device was attached to a video camera and then run through the line to the approximate location of the buried catch basin/manhole. A laborer on the surface would then use a jackhammer or other equipment to remove the surface material in the general area of that locating device's signal in order to uncover the catch basin/manhole. Following cleaning, several of these catch basins/manholes had to be raised or rebuilt to the existing grade (Appendix A, Photo 8).

Approximately 62 catch basins/manholes contained liquids which had to be removed prior to cleaning, while approximately 388 catch basins contained sediments which had to be removed (Appendix A, Photo 10). The sediments in many of the catch basin sediment traps were so cemented that they could not be removed by the jetting or the vactor truck. In these cases, a laborer was lowered into the catch basin to manually chip and break up the sediments so that they could be removed by the vactor truck.

Every effort was made during the project to properly distinguish a catch basin (CB) from a manhole (MH). Initially, a catch basin was defined for the project as a drainage structure with a sediment trap. However, several drainage structures had grated covers with no sediment trap, which classified them as catch basins.

A detailed log of the catch basins/manholes cleaned during the project is presented in Appendix C. The location of each catch basin/manhole is shown on the as-built drawings (Figures 3-1 through 3-10). The catch basin/manhole numbering system shown on the as-built drawings and

logs was developed for this project since the existing HPS numbering system did not cover the entire storm drain system.

2.5 Liquid Disposal

During times when high volumes of liquids were being removed during cleaning activities, the excess water stored in the four clean water storage tanks at the phase separation system had to be removed to provide new capacity for the system to continue to operate. This water was sampled and analyzed in order to obtain a permit from the City of San Francisco to discharge the water into HPS sanitary sewer system at Pump Station A. Approximately 1.3 million gallons of permitted water were discharged to the City during the project. Copies of the City of San Francisco Single Batch Discharge Permits are included in Appendix D.

2.6 Sediment Disposal

Sediments collected in the phase separators were initially placed in the temporary stockpile area. Later in the project, sediments remained containerized in the phase separators, which were then used to transport the sediments to their final disposal site. Over 1,200 tons of hazardous sediments were removed from the storm drain system during the project. These sediments were sampled and analyzed for the parameters shown in the project Sampling and Analysis Plan. Summary tables showing the analytical "hit" results for sediments sampled during the project in the stockpile area and later in the phase separators prior to their disposal are included in Appendix E. Overall, the analytical results indicated high concentrations of total petroleum hydrocarbons (TPH), metals (i.e., lead, copper), and polychlorinated biphenyls (PCBs), which determined the final disposal site. Following sampling, the stockpiled sediments were loaded onto trucks and transported for final disposal destination (Appendix A, Photo 12).

Based on the analytical results, approximately 680 tons of sediment were classified as a California hazardous waste, and approximately 210 tons of sediment were classified as a RCRA waste, based on metals (i.e., lead) concentrations above the toxicity characterization leaching procedure (TCLP) level, which required stabilization prior to landfilling. Both of the above waste classifications were disposed of at Chemical Waste Management's Class I landfill at Kettleman Hills, California.

From:		Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	To:MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A2-1	CB A2-2	8/VCP	12/16/96	300	0	1/28/97	300	0				
CB A3-1	CB A3-2	8/VCP	12/16/96	232	0	1/21/97	232	0				
CB A3-1	CB A3	8/conc.	12/16/96	200	0	1/21/97	220	0				
CB A6-7	CB A6-8	8/VCP	12/23/96	58	0	1/27/97	58	0				<u></u>
CB A7-1	lateral	8/VCP	1/16/97	145	11	4/23/97	156	0			<u> </u>	Not accessible for complete 1st line cleaning - 90° elbow
CB B13	CB B14	15/VCP	9/3/97	202	0							
CB B8-1	CB B8-2	10/VCP	5/14/97	165	0	6/17/97	165	0				
CB B8-5	мн в8	18/VCP	4/22/97	205	0						<u> </u>	
CB B8-5	СВ М3	8/RCP	4/23/97	170	0	5/1/97	170	0				
CB B8-5	CB B8-6	8/RCP	4/23/97	50	0	5/1/97	50	0				
CB C2	CB C3	15/VCP	5/1/97	215	0	5/6/97	215	0			ļ	
CB C2	lateral	6/VCP	5/2/97	120	0	5/13/97	75	45	9/2/97	120	0	Not accessible for complete 2nd line cleaning - debris
CB C2	CB C2-1	6/VCP	5/2/97	115	0	5/13/97	115	0				
CB C2	CB C2-2	12/RCP	5/5/97	170	0	5/6/97	170	0	<u> </u>			
CB C2-2	CB C2-3	12/RCP	5/5/97	180	0	5/6/97	180	0				
CB C2-2	lateral	8/RCP	5/5/97	82	82	5/6/97	164	0				Not accessible for complete 1st line cleaning - debris
CB C2-3	CB C2-4	10/RCP	5/5/97	150	0	5/6/97	150	0			ļ	
CB C2-4	CB C2-5	10/RCP	5/5/97	92	0	5/6/97	92	0	<u> </u>			
CB C3	CB C6	6/VCP	5/6/97	120	0	5/13/97	120	0	<u> </u>			
CB C3	CB C4	10/VCP	5/6/97	36	0	5/13/97	36	0				
CB C3	CB F3	15/VCP	5/6/97	28	0	5/13/97	28	0	ļ			
CB C3	CB C5	8/Corr	5/6/97	60	0	5/9/97	60	0				
CB E13	CB E15	15/VCP	2/4/97	157	0	3/26/97	157	0	ļ			
CB E13	CB E9	15/VCP	2/4/97	135	0	ļ] i	
CB E13	MH E14	21/VCP	2/5/97	120	0	5/6/97	120	0	 			
CB E15	Inlet E16	15/Corr	2/3/97	76	62	5/7/97	138	0	<u> </u>			Not accessible for complete 1st line cleaning - bend
CB E15	lateral	8/VCP	2/3/97	70	0	5/7/97	70	0	<u> </u>			
CB E15	MH E17	15/VCP	2/3/97	75	0	3/26/97	75	0	 			
CB E15	lateral	15/Corr.	5/7/97	75	55	6/17/97	130	0	 		 	Not accessible for complete 1st line cleaning - obstruction
CB E2-3	CB C5	8/Corr	5/6/97	153	0	5/9/97	153	0			 	Dualton line
CB E2-3	lateral	8/Corr.	5/6/97	146	154	5/9/97	146	154			 	Broken line
CB E3	MH E4	15/Metal	2/3/97	90	0	4/7/97	90	0			 	
CB E9	CB E11	12/VCP	2/4/97	60	0	5/16/97	60	0			 	
CB FI	CB P1-1	15/VCP	5/7/97	38	0	6/17/97	38	0			 	
CB F1	CB F2	48/RCP	5/7/97	245	0	5/8/97	245	0				
CB F2-1	CB F2	15/RCP	5/8/97	290	0	5/8/97	290	0				

From:		Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	To:MH/CB	Type of Pipe	Date	(ft)	(fi)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB F4 (thru F3	CB F2	48/RCP	5/8/97	250	0	5/9/97	250	0				
CB II	lateral	6/VCP	2/6/97	257	0	5/1/97	257	0				
CB 114	CB I14-1	12	5/6/97	60	0	6/17/97	60	0				
CB 114-2	CB 114-3	12/PVC	2/13/97	60	0							
CB 114-2	CB 114-1	12/PVC	2/13/97	54	0	9/2/97	54	0				
CB 114-3	CB I14-4	10/PVC	2/13/97	63	0							
CB 114-4	CB I14-5	8/PVC	2/13/97	60	0							
	lateral Bldg											
CB 13	406	6/CIP	2/6/97	257	()	4/30/97	257	0				
CB 18-3	CB 18-4	8/PVC	2/10/97	107	0	5/1/97	107	0				
CB 18-3	MH 18-1	10/PVC	2/10/97	90	0	5/1/97	90	0				
CB 19	CB 19-1	8/VCP	2/10/97	87	0	5/1/97	87	0				
CB 19-2	MH 19	8/PVC	2/12/97	51	0	5/5/97	51	0				
CB K3	CB K5	6/CSP	5/21/97	150	90	6/17/97	100	140				Not accessible for complete line cleaning - obstruction
CB L6	CB L7	8/Corr.	5/7/97	250	0	5/15/97	250	0				
CB L7	CB L8	8/Corr.	5/7/97	37	233						[Broken line
CB L7	MH L7-1	8	5/7/97	20	0							
CB L8	90 CBL9	6/Corr.	5/7/97	128	47	5/15/97	175	0				Not accessible for complete 1st line cleaning - 90° elbow
CB L9	90 CB L8	6/Corr.	5/7/97	55	0							
CB M3-1	CB M3	8/RCP	4/23/97	154	()	5/2/97	154	0				
CB N2	MH N1	8/VCP	5/14/97	100	0	6/17/97	100	0				
Div. Struct.						ŀ					}	
"B"	MH B1	24/VCP	1/14/97	20	0	4/30/97	20	0				
Div. Struct.												
"B"	MH B4	25/VCP	1/15/97	335	0	4/7/97	335	0				
MHAI	lateral	10/CIP	12/16/96	200	0							
MHAI	lateral	6/CMP	12/17/96	82	0	5/2/97	82	0				
MH A2	CB A2-1	8/VCP	12/16/96	188	0	1/21/97	188	0				
MH A2	MH A1	15/VCP	12/17/96	201	0	1/21/97	201	0				
MH A2	MH A3	18/VCP	12/17/96	202	0	1/28/97	202	0				
MH A3	MH A4	21/VCP	12/17/96	204	0	1/28/97	162	42				Not accessible for complete 2nd line cleaning - debris
MH A4	MH A5	21/VCP	1/13/97	200	0	1/28/97	200	0				
MH A5	MH A6	21/VCP	12/23/96	189	0	1/28/97	189	0				
MH A6	MH A6-1	21/VCP	12/13/96	154	0	1/27/97	140	0				
MH A6	MH A7	33/VCP	1/13/97	390	0	1/27/97	390	0				
MH A6-1	lateral	8/VCP	12/13/96	154	0	1/24/97	154	0				
MH A6-1	CB A6-1	8/VCP	12/16/96	6	0							

From:		Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	To:MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
MH A6-2	MH A6-3	6/VCP	12/13/96	170	0	1/24/97	170	0			 	
MH A6-2	CB A6-2	8/VCP	12/13/96	4	0		<u>.</u>				 	
MH A6-2	MH A6-1	15/VCP	12/13/96	165	0	1/24/97	165	0			i	
MH A6-2	lateral	5/VCP	12/13/96	40	0	5/2/97	40	0				
MH A6-4	MH A6	21/VCP	1/13/97	204	0	1/27/97	204	0				
MH A6-5	MH A6-6	18/VCP	12/26/96	202	0	1/27/97	202	0				
MH A6-5	lateral	8/VCP	12/23/96	58	100	1/27/97	58	100				Not accessible for complete line cleaning - obstruction
MH A6-5	MH A6-4	18/VCP	1/13/97	200	()	1/27/97	200	0			 	
MH A6-6	CB A6-7	8/VCP	12/23/96	21	0	1/27/97	21	0				
MH A7-1	MH A7	24/VCP	1/16/97	150	0	1/27/97	150	0				
MH A7-1	CB A7-1	8/VCP	1/16/97	5	0							
MH A7-2	MH A7-1	24/VCP	1/16/97	170	0	1/27/97	170	0				
MH A7-2	lateral	6/VCP	1/16/97	24	126	5/12/97	24	126				Broken line
MH A7-2	lateral	8/VCP	1/16/97	84	56	5/20/97	140	0				Not accessible for complete line cleaning - obstruction
MH A7-3	MH A7	18/VCP	1/14/97	210	0	1/27/97	210	0				
MH B1	МН С2	15/VCP	1/21/97	369	0	4/30/97	369	0				
MH B1	MH P4	18/VCP	5/8/97	180_	0	5/9/97	180	0				
MH B1	CB P3	10/VCP	5/8/97	140	0	5/9/97	140	0				
MH B1	MH B1-2	12/VCP	5/8/97	205	0	5/9/97	205	0				
	lateral Bldg											
MH B1-2	400	6/VCP	9/3/97	96	0							
MH B4	CB B4-1	10/VCP	1/15/97	186	0	4/7/97	186	0				
MH B4	MH B6	25/VCP	1/15/97	335	0	4/7/97	335	0				
MH B7	MH B6	31/VCP	4/7/97	204	0	4/7/97	204	0				
MH B8	MH B7	30/VCP	4/9/97	210	0	4/18/97	210	0				
MH B8	MH B9	36/Corr.	4/17/97	365	0	4/18/97	365	0				
MH B8	CB B8-1	15/VCP	9/3/97	145	0							
MH E17	CB E18	15/VCP	2/3/97	60	15	5/6/97	75	0				Not accessible for complete 1st line cleaning - obstruction
MH E2	CB E3	i 5/Metal	2/3/97	123	0	4/7/97	123	0				
MH E2	CB E13	36/Conc.	2/5/97	265	0	4/7/97	265	0				
MH E2	CB E1	15/VCP	4/7/97	106	0	5/6/97	106	0				
MH E2-1	MH E2	40/Conc.	2/5/97	105	0	5/1/97	105	0				
MH E2-1	MH E2-2	36/RCP	5/6/97	190	0	5/7/97	190	0				
MH E2-2	CB E2-4	15/RCP	5/6/97	106	0	5/7/97	106	0				
MH E2-2	CB F1	36/RCP	5/7/97	90	0	5/7/97	90	0				
MH E4	MH E5	15/Conc.	2/3/97	44	()	4/7/97	44	0				
MH E4	lateral	15/Corr.	1/30/97	40	80	4/7/97	40	80			<u> </u>	Broken pipe

From:	T	Pipe Dia. (in)/	1st Clean-up	Cleaned	Unalasmad	2nd Clean-up	Cleaned	Unalannad	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	To:MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date			Remarks
	 								Date	(ft)	(ft)	Remarks
MH E5 MH E5	CB E7	4/VCP	2/3/97 2/3/97	60	0	5/2/97	60	0			 	
	CB E6	12/Conc.		20		4/7/97	20	0			 	
MH F5	CB F4	54/RCP	5/9/97	420	0							
MH F5	MH F6	54/RCP	5/12/97	425	0							
MH G1	MH G2	15/VCP	1/21/97	400	0	4/1/97	400	00				
MH G2	lateral	8/VCP	1/21/97	15	135	5/20/97	150	0				Not accessible for complete 1st line cleaning - 90° elbow
MHII	lateral	6/VCP	2/10/97	32	68	5/1/97	32	68				Not accessible for complete line cleaning - obstruction
MH 110	lateral	12/VCP	2/12/97	79	0	6/17/97	79	0				
MH 110	MH III	15/VCP	2/18/97	49	0	5/5/97	49	0				
MH III	MH I12	15/VCP	2/18/97	36	0	5/5/97	36	0				
MH 110	MH 19	15/VCP	2/18/97	119	0	3/26/97	119	0				
MH III	CB 111-1	8/VCP	2/12/97	108	0	5/1/97	108	0				
MH 113-1	clean out	8/VCP	2/12/97	171	0	5/2/97	171	0				
MH 113-1	roof leader	8/PVC	2/12/97	15	165	3/27/97	170	0				Not accessible for complete 1st line cleaning - obstruction
MH 113-1	MH I13	8/PVC	2/12/97	63	0	3/27/97	47	0		·		
MH 12	MH II	15/VCP	2/5/97	184	0	3/25/97	184	0				
MH 12	MH 13	18/VCP	2/5/97	180	0	3/25/97	180	0				
	lateral Bldg											
MH 13	407	6/VCP	2/6/97	91	9	4/30/97	100	0			} }	
MH 13	lateral	6/VCP	2/10/97	30	0	5/7/97	30	0				
MH 14	MH I3	21/VCP	2/5/97	186	0	3/25/97	186	0	4/16/97	186	0	
MH 15	MH 14	24/VCP	2/5/97	131	0	3/25/97	131	0				
MH 17	MH 15	24/VCP	2/6/97	141	0	3/25/97	141	0				
MH 18	MH 17	24/VCP	2/6/97	104	0	3/25/97	104	_ 0_				
MH 18	MH 19	21/VCP	2/19/97	191	0	3/26/97	191	0				
MH 18-1	MH 18-2	12/VCP	2/6/97	62	0	3/25/97	62	0				
MH 18-1	MH 18	15/VCP	2/6/97	130	0	3/25/97	130	0				
MH 18-2	CB 18-5	6/PVC	2/10/97	121	0	5/1/97	121	0				
MH 19-3	roof drain	6/PVC	2/10/97	17	0							
MH 19-3	roof drain	6/PVC	2/10/97	20_	0							
MH 19-3	roof leader	8/PVC	2/10/97	60	()	6/17/97	47	13				Not accessible for complete 2nd line cleaning - broken
MH 19-3	CB 19-2	8/PVC	2/10/97	20	0	5/5/97	20	0				
MH J2	MH 18	36/VCP	2/20/97	324	0	3/31/97	324	0				
MH L10	90 MH L7-1	6/Corr.	5/7/97	135	0							
MH L10	CB L9	6/Corr.	5/7/97	80	0	5/15/97	80	0				
MH L10	lateral Bldg 707	6/Corr.	5/7/97	60	60	5/15/97	40	80		-		Mat appearable for a matter line about a
	<u> </u>	5, 50m.	20071			וקוטונו		00	l		<u></u>	Not accessible for complete line cleaning - debris

From:	T 1	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	To:MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
MH L7-1	lateral	6/Corr.	5/7/97	135	0_	6/17/97	100	35				
MH L7-1	708	6	5/7/97	24	0	6/17/97	3	21				Not accessible for complete 2nd line cleaning - obstruction
MH L7-1	90 MH L10	8/Corr.	5/7/97	125	0	5/15/97	125	0				
MH PI	MH B1	18/RCP	5/5/97	470	0	5/6/97	470	0			<u> </u>	
Are	a 1-1	8		0	390							Submerged lines
]		15		0	60							Submerged lines
Are	a 1-2	4		0	130							Submerged lines
		6		0	1790							Submerged lines
		8		0	1670							Submerged lines
		10		0	465							Submerged lines
j		12		0	110							Submerged lines
		18		0	580							Submerged lines
		21		0	140							Submerged lines
1		24		0	1340			1				Submerged lines
		30		0	615							Submerged lines
		42		0	800							Submerged lines
		48		0	2835							Submerged lines
		52		0	200							Submerged lines
		60		0	530							Submerged lines

From:	To:	Pipe Dia. (in)/	1st Clean up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Unalasad	3rd Clean-up	Cleaned	Uncleaned	
	MH/CB	- 1	· ·	(ft)				B	- 1			Dona Ju
CB A1-4	CB A1-X	Type of Pipe 8/VCP	Date 1/2/97	39	(ft) 0	Date 1/15/97	(ft) 39	(ft) 0	Date	(ft)	(ft)	Remarks
CB A1-X	MH A2	8 8	1/2/97	60	0	1/13/97	39					
												
CB A3-1	CB A1-Y	6/VCP	1/2/97	- 34	0							
CB A3-1	lateral	6	1/2/97	15	0							
CB A4-2	CB A4-3	8/CIP	1/6/97	112	0			ļ				
CB A4-3	GT A4-4	6/VCP	1/8/97	10	60			 				Not accessible for complete line cleaning - obstruction
CB A5-3	mainline	10	1/24/97	36	0							~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
CB A5-3	lateral	4/VCP	1/24/97	109	0	1/30/92	109	0				
CB D2	MH DI	8/VCP	11/27/96	40	0	12/18/96	40	0				
CB D3	CB D5	8	11/12/96	40	0							
CB D3	CB D4	8	11/12/96	40	0							
CB E1	CB E2	12/VCP	11/7/96	44	0	1/8/97	44	0	ii			
CB F2	main Line	8	12/3/96	51	0							
CB F3	main Line	8	12/3/96	60	0					_		
CB H1	CB H2	15/VCP	12/11/96	133	0							
CB H1	MH A9	18/VCP	1/3/97	98	0							
CB H2	CB H3	12/VCP	12/11/96	148	0						,	
CB H3	CB H4	10/VCP	1/8/97	55	0	1/15/97	55	0				
CB H3	CB H5	10/VCP	1/8/97	65	0							
CB H6	mainline	10/VCP	1/6/97	89	41							Not accessible for complete line cleaning - plastic substance
CB II	CB I2	15/VCP	12/5/96	150	0	12/31/96	150	0				
CB II	CB 15	12/VCP	12/5/96	111	0	12/31/96	111	0				
CB I2	CB 13	12/VCP	12/5/96	152	0	12/31/96	152	0				
CB I3	CB I4	12/VCP	12/5/96	88	0	12/31/96	88	0				
Diversion												
Struct.	MH A6	33/VCP	12/2/96	42	0	12/19/96	42	0	ļ	J		
MH A1	MH A1-Z	18/VCP	11/18/96	40	0							
MH A1	MH A2	21/VCP	11/18/96	60	0							
MH A1	lateral	12/VCP	11/20/96	64	0	1/14/97	64	0			*********** †	
MH A1-1	lateral	18/VCP	11/6/96	252	0	12/19/96	252	0	1/6/97	252	0	
MH A1-1	MH A1	18/VCP	11/20/96	34	0	12/18/96	34	0				
MH A1-1	lateral	12/VCP	12/18/96	34	0	1/6/97	22	12				Not accessible for complete 2nd line cleaning - broken
MH A1-2	MH A1-3	24/VCP	11/18/96	301	0	12/18/96	301	0	12/30/96	301	0	JORGE TO THE SECOND PARCE
MH A1-2	MH A1-Z	24/VCP	11/18/96	301	0	12/18/96	301	0				
MH A1-Z	lateral	15/VCP	1/7/97	57	0							
MH A1-Z	lateral	10/VCP	1/7/97	29	0							
MH A1-Z	lateral	4/VCP	1/8/97	50	0							
					<u></u> l	I.						

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
MH A3	MH A2	15/VCP	11/6/96	124	0	12/18/96	124	0				
MH A3	CB A3-1	8/VCP	1/2/97	55	0							
MH A3	lateral	8/VCP	1/2/97	25	0	1/15/97	25	0				
MH A4	MH A3	27/VCP	11/6/96	65	0	12/18/96	65	0				
MH A4	CB A4-1	8/VCP	11/6/96	22	0	12/19/96	22	0				
MH A4	CB A4-2	8/VCP	11/6/96	26	0	12/19/96	26	0				
MH A4	lateral	6/VCP	11/18/96	0	0							
MH A5	MH A4	27/VCP	11/6/96	283	0	1/6/97	280	0				
MH A5	MH A5-1	27/VCP	11/27/96	99	0							
MH A5	CB E1	12/VCP	11/7/96	110	0							
MH A5-1	CB A5-0	8/VCP	11/7/96	10	0							
MH A5-1	MH A5-2	24/VCP	11/27/96	70	0							
MH A5-2	мн сз	15/VCP	11/7/96	230	0	11/27/96	230	0				
MH A5-2	MH A5-4	18/VCP	11/7/96	238	0	11/26/96	238	0	1/6/97	238	0	
MH A5-4	lateral	18/VCP	11/6/96	95	0	12/19/96	95	0				
MH A5-4	CB A5-5	15/VCP	11/6/96	108	0	11/26/96	801	0				
MH A6	MH A5	30/VCP	11/27/96	273	0	11/28/96	273	0				
MH A6	MH D1	18/VCP	11/27/96	97	0	12/2/96	97	0				
MH A7	CB F1	10/VCP	12/3/96	338	0	12/18/96	338	0	L			
MH A7	lateral	33/VCP	12/4/96	82	16	1/3/97	98	0				Not accessible for complete 1st line cleaning - cave-in
MH A7	CB A7-1	12/VCP	1/7/97	30	0							
1 1	Diversion			İ]						
MH A7	Struct.	33/VCP	12/3/96	215	0	12/19/96	215	0				
MH A8	CB II	24/VCP	12/5/96	85	0	1/3/97	85	00				
MH A8	MH A7	36/VCP	12/27/96	177	0	1/3/97	177	_0				
MH A9	MH A8	36/VCP	12/31/96	217	0	1/3/97	217	0				
MH C3	CB C6	15/VCP	11/6/96	230	0	11/26/96	230	0	1/7/97	230	0	
MH C3	lateral	6/VCP	11/6/96	61	0	11/26/96	61	0				
MH C3	CB C2	8/VCP	11/6/96	10	0							
MH DI	CB D3	8/VCP	11/12/96	143	0	12/18/96	143	0	1/6/97	143	0	
MH D1	MH D7	15/VCP	12/2/96	186	0	12/2/96	186	0	12/18/96	186	0	
MH D7	CB D8	12/VCP	11/12/96	76	0	12/18/96	76	0				
MH D7	lateral	12/VCP	11/27/96	130	0	12/2/96	130	0				
MH D7	CB D10	8/VCP	11/27/96	30	0	12/18/96	30	0				
Area	2-1	4		0	110							Not accessible for cleaning - plugged
		6		0	75							Not accessible for cleaning - plugged
1	ĺ	10		0	100							Not accessible for cleaning - plugged
	l	12		0	140							Not accessible for cleaning - plugged

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A2	CB A1	10/VCP	12/12/96	131	0	1/9/97	131	0				
CB A2	Sump	4/CI	2/11/97	16	0							
CB B2	CB B1	8/VCP	1/9/97	120	0	2/5/97	120	0				
MH A3	CB A2	10/VCP	12/12/96	63	0	1/9/97	63	0	2/11/97	63	0	
MH A3	CB A3	10/VCP	12/12/96	10	0							
	lateral Bldg											
MH A3	123	4/VCP	2/11/97	65	()							
MH A4	MH A3	18/VCP	12/12/96	210	0	1/9/97	210	0				
MH A4	CB A4-1	12/VCP	12/12/96	264	0	1/9/97	264	0				
Are	ea 3-1	4		0	215							Submerged Pipe
		6		0	90							Submerged Pipe
İ		8		0	205							Submerged Pipe
1		10		0	55							Submerged Pipe
		14		0	125							Submerged Pipe
		24		0	185							Submerged Pipe

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB B5-3	CB B5-4	10 / VCP	2/18/97	227	()	2/19/97	227	0				
CB B6-3	MH B6-4	6 / VCP	10/17/96	55	()							
CB B6-6	lateral	6/CMP	10/17/96	60	0							
CB B7-1	CB B7-3	8 / VCP	10/23/96	53	()	1/8/97	53	0				
CB B7-2	CB B7-4	10 / VCP	10/23/96	44	0	1/8/97	44	0	2/3/97	44	0	
CB B7-2	CB B7-1	10 / VCP	10/23/96	115	0	1/8/97	115	0	2/3/97	115	0	
CB B7-5	CB B7-6	12 / VCP	10/22/96	113	0	1/8/97	113	0	2/3/97	113	0	
CB B7-7	CB B7-6	8 / VCP	10/22/96	147	0	1/8/97	147	0	2/3/97	147	0	
CB B7-8	Wye	8 / VCP	1/8/97	12	0	2/11/97	20	0				
CB B8-5	CB B8-6	8 / VCP	11/20/96	120	0	1/29/97	120	0				
CB B8-5	MH B8-4	8 / VCP	11/20/96	140	0	1/29/97	140	0_				
CB D2	CB D1	6/VCP	1/30/97	100	0	2/12/97	100	0				
CB E4	CB E3	8	12/2/96	182	0							
CB E5	CB E4	10/VCP	12/2/96	145	0	1/13/97	145	0	2/3/97	145	0	
						2/12/1997; 4K						
CB F3	lateral	4 / VCP	1/30/97	72	()	psi	72	0	_			
MH B5	MH B4	27/VCP		0	60							Damaged pipe
MH B5-1	MH B5	27/VCP	11/20/96	136	0	1/7/97	136	0				
MH B6	CB B6-1	12/VCP	11/29/96	200	0	1/7/97	200	0				
MH B6	CB B6-7	12/VCP	11/29/96	125	()	1/7/97	125	0				
MH B6	MH B5-1	36/VCP	11/21/96	204	0	1/7/97	204	0	ļ			
MH B6	MH B6-2	8 / VCP	10/17/96	165	0	1/7/97	165	0				
MH B6-3	MH B6-5	6 / VCP	10/17/96	61	0	1/7/97	61	0	2/3/97	61	0	
MH B6-6	lateral	6/CI	10/17/96	60	0							
MH B6-6	CB B6-3	8 / VCP	10/17/96	56	0	2/11/97	56	0				
MH B6-6	MH B6-2	8 / VCP	10/17/96	5	0	2/11/97	5	0				
	lateral/							[]
MH B7	Bldg 130	6 / VCP	10/17/96	20	()			 				
MH B7	MH B6	33/VCP	11/25/96	237_	0	1/7/97	237	0			ļ	
MH B7	MH B8	33/VCP	11/26/96	134	0	1/8/97	134	0				
MH B7	CB B7-5	15 / VCP	10/22/96	144	0	1/8/97	144	0	2/3/97	144	0	
MH B7	CB B7-1	12 / VCP	10/23/96	107	0	1/8/97	107	0	2/3/97	107	0	

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
MH B8	MH B9	33/VCP	11/26/96	50	0	1/8/97	50	0				
												:
MH B8	CB B8-1	18 / VCP	2/21/97	107	0	2/21/97	107	0				
MH B8-2	CB B8-1	15	11/20/96	270	0				d			
MH B8-3	MH B8-4	8 / VCP	11/20/96	88	0	1/29/97	88	0	2/19/97	88	0	
						2/19/1997; 4K						
MH B8-3	MH B8-2	12 / VCP	1/29/97	80	()	psi	80	0				
MH B8-8	Sump	6/CMP	1/29/97	88	0	2/19/97	88	0				
						2/19/1997; 4K			,			
MH B8-8	MH B8-2	10 / VCP	1/30/97	296	()	psi	296	0				
MH B5-5	Mainline	12 / VCP	5/20/97	20	0							Line was plugged after it had been cleaned
ARE	A 4-1	12		0	50							Damaged pipe

From:	To:	Pipe Dia. (in)	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A3	CB A4	8/VCP	2/10/97	43	0	3/19/97	43	0				
CB A6	ST A6-X	4/CI	2/11/97	27	0	4/15/97	27	0				
CB A6	mainline	6	2/11/97	3	0							
	lateral Bldg										1	
CB A7	211	4/CI	5/9/97	30	()							
								ł	{	ł	1	
CB B1	CB B1-2	8/VCP	3/10/97	85	0	3/31/97	85	0	4/1/97	85	0	
CB B1	CB B2	30/VCP	3/11/97	90	0	3/18/97	90	0	<u> </u>			
CB B1	lateral	6/VCP	3/27/97	25	0	4/4/97	25	0				
CB B1	lateral	8/VCP	3/27/97	0	0				<u></u>			
									ŀ]	<u> </u>
CB B1-1	CB B1	10/VCP	3/10/97	83	()	4/2/97	83	0	4/4/97	83	0	
CB B1-2	CB G8	8/VCP	3/27/97	80	0	4/1/97	80	0				
	lateral Bldg								[ĺ	[[
CB B1-2	226	6/VCP	3/27/97	11	()						ļ	
		i I		!		}			4/4/97	147	0	
CB B10	CB B10-5	10/VCP	2/12/97	147	()	3/5/97; 4K psi	147	0	4/11/97	147	0	
		ļ				ŀ				1		
CB B10	CB B10-2	10/VCP	2/12/97	115	0	3/5/97; 4K psi	115	0	4/11/97	115	0	
CB B10-1	lateral	4/VCP	4/9/97 4K psi	45	0					!		
CB B10-2	lateral	8/VCP	2/12/97	15	0			<u> </u>		ļ	 	
CB B10-4	CB B10-2	10/VCP	2/12/97	19	0	3/5/97; 4K psi	19	0	ļ			
CB B10-6	CB B10-7	6/VCP	2/12/97	103	0	3/5/97; 4K psi	103	0		ļ		
CB B10-6	CB B10-5	8VCP	2/12/97	41	0	3/5/97; 4K psi	41	0				
CB B3	lateral	12/VCP	3/12/97	40	40	3/17/97	40	40				Not accessible for complete line cleaning - collapsed
CB B3	CB B5	27/VCP	3/12/97	235	0	3/13/97	235	0	4/11/97	235	0	
CB B3	CB B2	27/VCP	3/12/97	20	0	3/18/97	20	0		ļ		
CB B3-1	CB B3	10/VCP	3/12/97	111	0	3/17/97	111	0	ļ	ļ		
CB B3-2	CB B3-1	6/CI	3/13/97	40	0	3/17/97	40	0	4/14/97	40	0	
CB B5	MH B5-1	10/VCP	3/26/97	91	0	3/31/97	91	0	4/4/97	91	0	
CB B5	CB B7	30/VCP	3/10/97	187	0	3/19/97	187	0	3/25/97	187	0	
CB B5-1	lateral	6/VCP	3/26/97	15	50	4/4/97	65	0		<u> </u>	 	Not accessible for complete 1st line cleaning - damaged
CB B6	CB B6-1	18/VCP	3/5/97	75	0			 				
CB B6	CB B5	18/VCP	3/10/97	85	0	3/26/97	85	0				
CB B6-1	CB B6-3	15/VCP	3/10/97	115	0	4/1/97	115	0		 		
CB B6-1	CB B6-2	15/VCP	3/10/97	30	0	4/1/97	30	0	L	<u> </u>		

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date Date	(ft)	(ft)	Remarks
		1700 01 1.1/2						<u>\:\</u>	17die	(11)	- /::/	CHAIKS
CB B6-11	CB B6-8	12/VCP	3/4/97	155	0	3/6/97; 4K psi	155	0]]]	
			32. 32. 5			<u> </u>		<u>×</u>			· · · · · · · · · · · · · · · · · · ·	
CB B6-13	CB B6-11	8/CI	3/4/97	257	0	3/5/97; 4K psi	257	0	4/11/97	257	0	
CB B6-14	CB B6	15/VCP	3/5/97	90	0	3/25/97	90	0	3/25/97	90	0	
1		- 12: - 21				5.25.51			3.2377		l — Š	
CB B6-14	CB B6-2	15/VCP	3/6/97	93	0	3/25/97	93	0	}		}	-
CB B6-3	lateral	8	2/11/97	3	0							
CB B6-4	lateral	8/VCP	2/11/97	10	0	4/2/97	10	0				
CB B6-4	CB B6-3	15/VCP	2/11/97	67	0	4/2/97	67	0				
CB B6-8	CB B6-9	15/VCP	3/4/97	205	0	3/26/97	205	0				
CB B6-9	lateral	4/VCP	2/26/97	25	65							Not accessible for complete line cleaning - obstruction
CB B6-Y	CB B6-2	10/VCP	2/11/97	50	()	4/2/97	50	0				
CB B6-Y	lateral	6/VCP	3/10/97	80	()	4/2/97	80	0				
CB B6-Y	lateral	10/VCP	3/10/97	80	0	4/2/97	80	0				
CB B7-1	CB B7	10/VCP	3/27/97	38	0	4/4/97	38	0				
CB B7-1	lateral	10/VCP	3/27/97	62	0	4/4/97	45	17				Not accessible for complete 2nd line cleaning - debris
CB B8	MH B7	12/VCP	2/25/97	228	0	3/25/97	228	0	3/25/97	228	0	<u> </u>
CB B8-1	CB B8-2	10/VCP	2/24/97	112	0	3/26/97	112	0				
CB B8-1	lateral	8/VCP	2/24/97	41	0	3/26/97	41	0				
CB B8-1	CB B8	10/VCP	2/25/97	28	0	3/6/97; 4K psi	28	0	3/27/97	28	0	
1 1												
CB B9	CB B10	12/VCP	2/24/97	250	()	3/6/97; 4K psi	250	0	4/17/97	250	0	
CB B9	CB B8	12/VCP	2/25/97	239	0	3/6/97; 4K psi	239	0	4/4/97	239	0	
CB B9	lateral	8	3/6/97	0	0							
CB B9-1	CB B9	10/VCP	2/24/97	33	0	3/13/97; 4K psi	33	0				
CB B9-1	CB B9-2	10/VCP	2/24/97	102	0	3/13/97	102	0	4/4/97	102	0	
CB B9-2	CB B9-3	10/VCP	2/24/97	17	0	3/13/97	17	0				
CB B9-3	lateral	4	2/24/97	0	170							Collapsed line
CB B9-3	lateral	6/VCP	3/26/97	140	()							
CB C2	CB C3	8/VCP	2/27/97	40	99	3/4/97; 4K psi	139	0				Not accessible for complete 1st line cleaning - obstruction
1	lateral Bldg											
CB C2	206	8/VCP	3/4/97	110	0							
CB D1	CB D1-3	10/VCP	3/4/97	84	0	4/1/97	84	0				
CB D1-1	CB D1-2	15/VCP	2/25/97	169	0	3/13/97	169	0	4/4/97	169	0	
CB D1-1	CB D1	12/VCP	2/26/97	67	0	3/13/97	67	0				
CB D1-2	lateral	8/VCP	2/25/97	36	160	3/13/97	36	160	3/26/97	36	160	Not accessible for complete line cleaning - bend
CB D2	CB D2-1	10/VCP	2/26/97	29	0	3/24/97	29	0	4/11/97	29	0	
CB D2	CB D1	15/VCP	2/26/97	100	0	3/24/97	100	0	4/4/97	100	0	

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB D3-1	lateral	4/VCP	2/26/97	55	0	4/15/97	55	0			1	
CB D5	lateral	4/VCP	2/26/97	166	0							
CB D5	mainline	10/VCP	2/26/97	30	0	4/1/97	30	0			1	
CB D6	mainline	10/VCP	4/8/97	30	0	4/9/97 4K psi	30	0				
	lateral Bldg											
CB E4-2	219	4/CI	4/9/97 4K psi	38	0				}		}	
CB E4-2	lateral	4/ABS	4/9/97 4K psi	60	0							
CB E6	mainline	8/VCP	4/8/97	32	0	4/8/97 4K psi	26	6				Not accessible for complete 2nd line cleaning - bend
CB F2	CB F2-2	8/CIP	3/3/97	148	0	3/5/97; 4K psi	148	0	4/4/97	148	0	
CB F2	CB F2-1	8/VCP	3/4/97	148	0	3/5/97; 4K psi	148	0				
	lateral Bldg											
CB G1	253	_10/VCP	3/18/97	26	()	3/31/97	26	0				
	lateral Bldg	-										
CB G1	253	10/VCP	3/18/97	28	0	3/31/97	28	0	4/3/97	28	0	
CB G2	CB G1	10/VCP	3/5/97	94	0	3/31/97	94	0				
CB G2	253	18/VCP	3/18/97	57	0	3/31/97	46	11				Not accessible for complete 2nd line cleaning - crushed
CB G2	lateral	8/VCP	3/18/97	27	0	3/31/97	27	0				
CB G2	CB G3	18/VCP	3/27/97	90	()	4/1/97	90	0	4/3/97	90	0	
CB H2	CB H2-1	10/VCP	3/27/97	44	0	4/1/97	44	0				
CB H2	СВ Н1	10/VCP	3/27/97	150	0	4/1/97	150	0				
CB H2-2	CB H2	10/VCP	3/25/97	100	0	3/27/97	100	0	4/1/97	100	0	
CB II	CB I1-1	10/VCP	3/12/97	97	0	3/31/97	97	0				
CB II	CB B3	12/VCP	3/13/97	348	0	3/13/97	348	0				
CB 12	CB II	10/VCP	3/27/97	200	0	3/31/97	200	0				
MH A1	CB A3	15/VCP	2/10/97	145	0	3/19/97	145	0				
MH A1	MH A5	15/VCP	2/10/97	180	0	3/24/97	180	0	4/14/97	180	0	
MH A1	CB A2	8/VCP	2/10/97	18	- 0	3/19/97	18	0				
1	Div. Struct,	ì	1	-								
MHAI	"A"	15/VCP	2/10/97	35	()	4/2/97	35	0				
	Div. Struct.											
MH A1-2	"A"	15/VCP	4/8/97	32	()	4/9/97 4K psi	32	0				
MH A1-2	CB A1-1	12/VCP	4/8/97	8	0	4/9/97 4K psi	8	0				
MH A1-3	MH A1-2	10/VCP	4/8/97	115	0	4/8/97	115	0				
MH A5	CB A7	12/VCP	2/10/97	345	0	3/19/97	345	0	4/3/97	345	0	
MH A5	CB A5-1	8/VCP	2/10/97	40	0	3/19/97	40	0				
MH B6-14	CB B6-6	15/VCP	3/4/97	178	0	3/25/97	178	0	3/26/97	178	0	
МН С4	CB C5	12/VCP	3/3/97	281	0	3/4/97; 4K psi	281	0				

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
	lateral Bldg											
MH C4	206	12/VCP	2/27/97	57	58	3/4/97; 4K psi	115	0				Not accessible for complete 1st line cleaning - 90° elbow
MH C6	MH C5	15/VCP	3/3/97	106	0	3/4/97; 4K psi	106	0	4/4/97	106	0	
MH C6	МН С7	15/VCP	3/3/97	57	0	3/4/97; 4K psi	57	0	4/4/97	57	0	
MH D1	CB B7	18/VCP	2/27/97	407	0	3/25/97	407	0	4/4/97	407	0	
MH D2	CB D2-2	10/VCP	2/27/97	27	0	3/24/97	27	0				
MH D3	CB D2	12/VCP	2/26/97	221	0	3/18/97	221	0	4/4/97	221	0	
MH D3	CB D3-1	10/VCP	2/27/97	38	0	4/2/97	38	0				
MH E1	roof drain	6/VCP	3/4/97	13	()							
MH E1	MH E2	10/VCP	3/4/97	177	0	3/6/97; 4K psi	177	0				
	lateral Bldg											
MH E2	231	6/VCP	3/4/97	18	0	3/26/97	18	0				
MH E2	MH E3	10/VCP	3/4/97	159	0	3/26/97	159	0	4/8/97	159	0	
MH E3	CB E3-1	8/VCP	4/8/97	32	0							
MH E4	MH E3	15/VCP	3/5/97	197	0	3/31/97	197	0				
MH E4	CB E5	8/VCP	3/5/97	117	0	3/31/97	117	0				
MH E4	CB E4-2	12/VCP	3/5/97	164	0	3/31/97	164	0				
MH E4	lateral	8/VCP	3/5/97	30	0	3/31/97	30	0				
MHFI	CB F2	10/VCP	3/4/97	35	0	3/5/97; 4K psi	35	0				
MH F1	lateral	12/VCP	3/4/97	37	0	4/1/97	37	0				
MHFI	CB B6-6	12/VCP	3/4/97	198	0	3/5/97; 4K psi	198	0			}	
MH D3	CB D3-2	10		0	70							Collapsed line
Are	a 5-1	4		0	100							Submerged lines

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A1	CB A1-1	10 / VCP	10/21/96	87	0	2/20/97	87	0	3/13/97	87	0	
CB A1	CB A1-3	10 / VCP	10/21/96	87	0	2/20/97	87	0	3/13/97	87	0	
CDAI	CDMIS	107 751	10/21/20									
CB A1	CB A2	15 / VCP	10/24/96	260	0	2/20/97	177	0	4/2/97	260	0	
CB A1-1	CB A1-2	10 / VCP	10/21/96	156	0	2/20/97	156	0				
CB A1-3	CB A1-4	10/CP	10/21/96	85	0	2/20/97	85	0				
	lateral (Bldg											
CB A1-3	241)	3 / CI	10/24/96	52	0	2/20/97						
CB A1-3	CB A1-5	4 / VCP	10/24/96	15	0	2/20/97	15	0				
CB A2	CB A2-1	12 / RCP	10/24/96	25	0	2/20/97	25	0				
CB A2-1	lateral	6 / CI	10/24/96	400	0							
CB A2-1	lateral	8 / VCP	10/24/96	310	0	2/20/97	310	0			l	
CB A3	CB A2	18 / VCP	10/25/96	125	0	11/15/96	125	0				
CB A4	CB A3	18 / VCP	10/25/96	150	0	11/15/96	150	0				
CB A4	lateral	10 / VCP	10/28/96	65	110	2/26/97	65	110				Not accessible for complete line cleaning - pipe diameter change
CB A4	CB A5	27 / VCP	10/30/96	220	0	11/25/96; 6K psi	220	0				
CB A4-1	lateral	18 / VCP	10/25/96	43	77	2/21/97	43	77				Not accessible for complete line cleaning - damaged
CB A4-1	CB A4-2	24 / VCP	10/25/96	275	0	2/20/97	275	0	3/13/97	275	0	
CB A4-1	CB A4	24 VCP	10/25/96	123	0	2/21/97	123	0	3/13/97	123	0	
CB A4-4	lateral	4/VCP	10/28/96	16	0	2/20/97	16	0				
CB A4-5	CB A4	15 / VCP	10/28/96	53	0	11/15/96	53	0	3/13/97	53	0	
									3rd 3/13/97	202	0	
CB A4-5	CB A4-4	12 / VCP	10/28/96	202	0	11/15/96	202	0	4th 3/17/97	202	0	
CB A5	CB A6	27 / VCP	10/30/96	272	0	2/21/97	272	0				
CB A5-1	lateral	4/VCP	2/19/97	3	0							
CB A5-3	lateral	6	2/13/97	3	0	2/19/97	3	0				
CB A5-3	mainline	10/VCP	2/13/97	71	0	2/19/97	71	0				
CB A6	CB A7	30/VCP	11/13/96	80	0	2/21/97	80	0				
CB A6	Div. Structure	12	11/13/96	20	0							
CB A6-1	CB A6-4	10/VCP	11/4/96	140	0	2/20/97; 4K psi	140	0				

		B: B: (: V		Classia	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned		2nd Clean-up Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
мн/св	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(11)	(10)	3rd 3/17/97	213	0	RCHarks
	OD 4.6	15 T (OD	11/12/06	212	0	11/14/96	213	0	3fd 3/1//9/ 4th 4/2/97	213	0	
CB A6-1	CB A6	15/VCP	11/13/96	213	0			0	4/2/97	103	0	
CB A6-2	CB A6-3	8/VCP	11/4/96	103	0	2/21/97; 4K psi	103		·			
				120		11/14/06	120		3rd 3/13/97 4th 4/2/97	130 130	0	
CB A6-2	CB A6-1	15/VCP	11/4/96	130	0	11/14/96	130	0	4th 4/2/97	130	<u> </u>	
CB A6-2	lateral	4/VCP	11/4/96	54	0	2/25/97	54					
l <u>.</u> . l	lateral/					0.004/07 416	5.0		441.5107	26	20	Mary address to a part of the state of
CB A6-4	Bldg 203	8 / VCP	11/4/96	56	0	2/24/97; 4K psi	56	0	4/15/97	36	20	Not accessible for complete 3rd line cleaning - bend
CB A6-4	lateral	8	11/4/96	30	0	0.001.000	205					
CB A7	MH A8	30/VCP	11/13/96	205	0	2/21/97	205	0				
CB A7-2	CB A7-3	8/VCP	2/19/97	60	0	2/19/97	60	0	 			
CB A7-2	mainline	8/VCP	2/19/97	75	0	2/19/97	75	0				
CB A8	CB A9	30/VCP	11/13/96	157	0	2/24/97	157	0	ļ			
CB A8	CB A8-1	12/VCP	11/14/96	97	0	2/21/97	97	0	2/25/97; 4K psi	97	0	
CB A8-1	lateral	4/VCP	11/14/96	80	0	2/18/97	80	0				
CB A8-2	CB A8-1	10/VCP	11/14/96	65	0	2/18/97; 4K psi	65	0	2/25/97	65	0	
CB A8-2	lateral	8/VCP	2/18/97	32	0	2/25/97	32	0	<u> </u>			
CB A8-2	lateral	4/VCP	2/18/97	22	0	2/25/97	22	0	ļ <u> </u>			
CB B1	CB B4	8/Conc.	11/13/96	33	63	2/21/97; 4K psi	33	63	2/25/97	96	0	Not accessible for complete 1st & 2nd cleaning - debris
CB B1	CB B2	8/VCP	11/13/96	55	0	2/21/97; 4K psi	55	0				
CB B1	CB B3	12/Conc.	11/13/96	54	0	2/21/97	54	0	2/25/97	54	0	
CB B3	outfall	12/VCP	11/13/96	90	0	2/27/97	90	0				
CB F1	mainline	4	3/18/97	103	0	3/18/97	103	0				
MH A5-1	MH A5-2	10/VCP	2/13/97	57	0	2/19/97; 4K psi	57	0	2/25/97	57	0	
MH A5-1	mainline	10/VCP	2/13/97	75	0	2/19/97; 4K psi	75	0	2/25/97	75	0	
MH A7	CB A7-1	8/VCP	11/13/96	71	0	2/24/97; 4K psi	71	0	2/25/97	71	0	
	lateral/					ļ]		j	
MH D1	mainline	10/VCP	2/24/97	197	0	2/24/97	197	0	2/26/97	197	0	
MH D2	MH D1	12/VCP	2/24/97	118	0	2/24/97	118	0	<u> </u>			
MH D2	CB D2-1	10/VCP	2/24/97	74	0	2/24/97	74	0				
MH D2	lateral	10/VCP	2/24/97	20	0	2/24/97	20	0				

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A1	CB A2	24/RCP	5/12/97	69	0	5/15/97	69	0		<u> </u>	\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.	
CB A1	CB E7	18/VCP	5/13/97	210	0	5/15/97	210	0	9/2/97	210	0	
CB A12	mainline	10/VCP	6/11/97	80	0	6/11/97	80	0		2.0	<u>`</u>	
CB A12	302	6	6/11/97	50	0	5/11/27		<u>*</u>	<u> </u>			
CB A13	mainline	8/CIP	6/10/97	100	0	6/10/97	100	0	9/2/97	100	0	
CB A3	CB A3-1	8/VCP	5/20/97	100	0	5/28/97	100	0	7121 <u>71</u>	100		
CB A6	MH A5	24/VCP	5/14/97	106	0	5/15/97	106	0				
CB A0	lateral Bldg	24/ VCI	3/14/7/	700		3/13/71	100		[
CB A6	366	12/VCP	5/14/97	340	0	5/19/97	300	40				Not accessible for complete 2nd line cleaning - pipe diameter change
CB C12-2	lateral	4/VCP	5/13/97	40	0	5/28/97	40	0				
CB C12-2	CB E6	12/RCP	5/13/97	145	0	5/19/97	145	0	9/2/97	145	0	
CB E1-1	CB E1-2	8/VCP	4/28/97	137	0	5/19/97	137	0				
CB E1-1	CB EI	8/VCP	4/28/97	147	0	5/19/97	147	0				
CDLII	lateral Bldg	<u> </u>	<u> </u>		<u> </u>					··		
CB E1-1	400	6/VCP	4/28/97	35	65	!						Not accessible for complete line cleaning - offset joint
CB E2	CB E2-1	10/VCP	4/28/97	35	0	5/28/97	35	0				
CB E2	CB E1	18/RCP	4/28/97	52	143	5/20/97	195	0				Not accessible for complete 1st line cleaning - debris
CB E3-3	CB E4-4	12/VCP	4/29/97	102	0	5/16/97	102	0				
CB E3-3	lateral	10	4/29/97	2	0							
CB E3-4	CB E3-3	8/VCP	4/29/97	133	0	5/16/97	133	0				
<u>*==-</u>	lateral Bldg											
CB E6	302	4/VCP	5/13/97	45	35	5/28/97	35	45				Not accessible for complete line cleaning - debris
CB E6-3	мн е6	8/VCP	5/14/97	110	0	5/27/97	110	0				
CB E7	MH E6	18/VCP	5/13/97	186	0	5/15/97	186	0				
CB E7	CB E7-1	8/VCP	5/13/97	57	0	5/15/97	57	0				
CB E7	CB E7-2	10/RCP	5/13/97	92	0	5/15/97	92	0				
MH A4	CB A3	24/RCP	5/13/97	208	0	5/15/97	208	0				
MH A4	CB A4-2	10/VCP	6/10/97	100	0	6/10/97	100	0				
MH A5	MH A4	24/RCP	5/13/97	272	0	5/15/97	272	0				

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
	lateral Bldg									1	Ì	
MH A5	366	12/VCP	5/14/97	85	255	5/22/97	85	255			<u> </u>	Not accessible for complete line cleaning - bend
MH A8	CB A6	24/RCP	5/14/97	163	0	5/15/97	163	0				
MH A8	MH A9	24/RCP	5/15/97	200	0	5/27/97	200	0				
мн а9	MH A10	24/RCP	5/15/97	200	0	5/27/97	200	0				1207
MH C12	CB C12-3	10/VCP	5/12/97	53	0	5/28/97	53	0				
MH C12	CB C12-2	10/RCP	5/12/97	45	45	5/28/97	90	0				Not accessible for complete 1st line cleaning - broken
MH E2	MH E3	18/VCP	4/28/97	100	0	5/23/97	100	0				
MH E3	CB E3-3	12/VCP	4/28/97	44	0	5/16/97	44	0				
MH E3	CB E3-2	10/VCP	4/29/97	44	0	5/23/97	44	0				
MH E3	MH E4	18/VCP	4/29/97	92	0	5/27/97	92	0				
MH E3	CB E3-1	10/VCP	4/29/97	18	0	5/27/97	18	0				
MH E4	CB E4-1	10/VCP	4/29/97	34	0	5/27/97	34	0				
MH E4	CB E4-2	10/VCP	4/29/97	58	0	5/27/97	58	0	<u> </u>			
MH E4	lateral	10/VCP	4/29/97	94	146			<u></u>				Not accessible for complete line cleaning - plugged
MH E4	CB E4-5	10/VCP	6/10/97	100	0	6/11/97	100	0				
MH E5	CB E5-1	8	4/29/97	7	0							
MH E5	МН Е6	18/VCP	4/29/97	191	0	5/27/97	191	0				
MH E5	lateral	8	5/14/97	38	0							
MH E5	MH E4	18/VCP	4/29/97	191	0	5/15/97	191	0				
MH E6-4	MH E6-1	8/VCP	5/13/97	86	0	5/28/97	86	0				
Area	7-1	2		0	65							Not accessible for cleaning
		3		0	25				L			Not accessible for cleaning
		6		0	35			<u> </u>				Not accessible for cleaning

				GI 1		2 1 01	011	111	2-4 Class	Classed	Linglaged	
From:	То:		1st Clean-up			2nd Clean-up		l .	3rd Clean-up	Cleaned	Uncleaned	Domestra
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A20	mainline	10/VCP	6/17/97	165	0	6/17/97	165	0				The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s
CB A8-1	downspout	6/PVC	4/24/97	20	0	5101105						
CB A8-1	downspout	8/PVC	4/24/97	67	0	5/21/97	67	0				
CB B4	MH D1	10/RCP	4/15/97	54	()						ļ	
CB B4	CB B4-1	10	4/15/97	3	0	4/30/97	3	0				
	lateral Bldg									i		
CB B4	411	12/RCP	4/15/97	30	10	5/29/97	40	0				Not accessible for complete 1st line cleaning - WYE
CB B4	MH B3	18/RCP	4/16/97	315	0	4/30/97	315	0				
CB B5	CB B6	18/Corr	4/28/97	106	0	5/15/97	106	0				
CB B5	CB B4	18/Согг	4/28/97	145	0	5/15/97	145	0				
CB B7-2	MH B7'	10/VCP	4/23/97	98	()	5/5/97	98	0				
CB D2	lateral	6/RCP	4/15/97	40	()			ļ				
CB D2	CB D2-2	10/VCP	4/15/97	200	0	4/29/97	200	0			 	
CB D2	MH DI	10/VCP	4/15/97	125	0	4/29/97	125	0				
CB E2-2	MH E2-1	10	4/15/97	4	0	4/29/97	44	0				
CB E3-1	CB E3-2	8/VCP	4/14/97	94	0	4/29/97	94	0				
CB E3-1	outfall	10/RCP	4/14/97	135	0	4/29/97	135	0				
CB E8	mainline	8/Corr	4/15/97	25	0	6/16/97	25	0				
	lateral Bldg											
MHAI	402	8/VCP	4/14/97	166	0	4/21/97	166	0				
MH A11	MH A10	10/RCP	4/22/97	73	0	5/5/97	73	0				
MH A2	MH A1	12	4/14/97	210	0							
MH A3	MH A2	15	4/15/97	165	0				-			
MH A3	MH C1	15/VCP	4/16/97	117	0	4/22/97	117	0				
MH A4	мн аз	21	4/15/97	433	0							
MH A5	MH A4	24	4/15/97	187	0							
MH A6	MH A5	24	4/15/97	103	0							
MILAG	lateral Bldg	- 	17 13757	105	<u>-</u>			†				The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon
MH A6	439	12/RCP	4/15/97	75	0	5/29/97	75	0				
MH A7	MH A6	27/RCP	4/15/97	88	0			1				
MH A8	MH A9	18/RCP	4/23/97	50	0	5/15/97	50	0				
MH A8	CB A8-1	8	4/24/97	55	0	5/15/97	55	0				
MH A8	MH A7	18/RCP	4/24/97	125	0	5/15/97	125	0				
MH A9	MH A17	8/PVC	4/22/97	120	0	5, 15, 7	— • = =					
MH A9	MH A10	10/RCP	4/22/97	110	0			<u> </u>				
MH B1	CB B1-1	10/10/	4/15/97	3	0							
MHBI	MH B2	15/RCP	4/15/97	180	0	4/29/97	180	0				
	CB B2-1	10/RCF	4/15/97	3	0	71271	100	<u> </u>				
MH B2	CD D2-1	10	4/13/97		U			L		L	L	

TABLE B-8 (a) BASIN VIII STORM DRAIN LINE CLEANING SUMMARY LOG

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
мн/св	мн/св	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
	lateral Bldg						· · · · · · · · · · · · · · · · · · ·					
MH B2	411	4/CIP	4/28/97	20	0	6/16/97	20	0			i l	
	lateral Bldg											
MH B2	366	4/CIP	4/28/97	30	0	6/16/97	20	10				Not accessible for complete 2nd line cleaning - obstruction
MH B3	MH B2	18/RCP	4/16/97	100	0	4/30/97	100	0				
MH B5	clean out	10/Corr	4/24/97	280	0	5/14/97	280	0				
MH B6-1	clean out	10/Corr.	4/17/97	135	0	5/21/97	135	0				
MH B6-1	CB F3	10/Согг.	4/17/97	50	0	5/21/97	50	0				
MH B6-1	CB B6	10/Corr	4/28/97	200	0	5/15/97	200	0				
MH B7	мн в6	24/RCP	4/25/97	120	0	4/30/97	120	0				
	MH A7 (thru											
MH B7	CB-2)	27/RCP	4/24/97	390	0							
MH B7	Div. Struct.	36/RCP	4/30/97	290	0	5/2/97	290	0				
MH B7-2	MH B8	8/VCP	4/23/97	213	0	4/30/97	213	0				
МН В9	mainline	10/VCP	4/21/97	28	0	6/16/97	28	0				
MH C2	MH C1	15/RCP	4/16/97	57	0	4/21/97	57	0				
MH C2	MH C6	10/RCP	4/16/97	135	0	4/21/97	135	0				
MH C2	CB C2-1	10	4/16/97	5	0	4/21/97	5	0				
MH C3	MH C4	12/RCP	4/16/97	180	0	4/21/97	180	0				
MH C3	MH C2	12/RCP	4/16/97	121	0	4/21/97	121	0				
мн сз	CB C3-1	10	4/16/97	5	0	4/21/97	5	0				
MH C3 (thru											1	
C9)	MH C7	10/RCP	4/16/97	138	0	4/21/97	138	0				
MH C4	MH C5	10/RCP	4/15/97	135	0	4/21/97	135	0				
MH C4	CB C4-1	10	4/15/97	8	0	4/21/97	8	0				
	lateral Bldg							·				
MHDI	351A	6	4/15/97	3	0	4/29/97	3	0				
MH E2	CB E2-3	15	4/14/97	3	0	4/29/97	3	0				
MH E2	CB E2-2	15/VCP	4/14/97	200	0	4/29/97	200	0				
MH E2	MH E2-4	18/VCP	4/14/97	290	0	4/29/97	290	0				
MH E2	MH E3	42/RCP	5/1/97	137	0	5/2/97	137	0				
MH E2-4	CB E2-5	10	4/15/97	3	0	4/29/97	3	0				
MH E2	Div. Struct.	42/RCP	5/1/97	95	0	5/2/97	85	0				
MH E3	lateral	8/RCP	4/14/97	128	0	5/29/97	128	0				

TABLE B-8 (a) BASIN VIII STORM DRAIN LINE CLEANING SUMMARY LOG

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
Area	ı 8-1	4		0	240							Not accessible for cleaning
Ī		8		0	300							Not accessible for cleaning
Area	a 8-2	8		0	170							Not accessible for cleaning
j		10		0	180							Not accessible for cleaning
		12		0	70							Not accessible for cleaning
Area	a 8-3	8		0	205							Not accessible for cleaning
		10		0	110							Not accessible for cleaning
Area	a 8-4	6		0	1705			<u> </u>				Not accessible for cleaning
J		8		0	60							Not accessible for cleaning

TABLE B-9 (a) BASIN IX STORM DRAIN CLEANING SUMMARY REPORT

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
CB A2-2	CB A2-3	8/VCP	5/16/97	55	0	5/30/97	55	0				
CB A2-2	MH A2	10/VCP	5/16/97	80	0	5/30/97	80	0				
CB A4-2	CB A4-3	12/RCP	6/11/97	125	()	6/11/97	125	0				
CB A4-2	MH A4	12/RCP	6/11/97	55	0	6/11/97	55	0				
CB A4-2	lateral	4/CIP	6/11/97	50	0	6/13/97	50	0				
CB A5	CB A5-1	12/VCP	6/12/97	100	0	6/16/97	100	0				
CB A6	mainline	10/VCP	6/16/97	80	()	6/16/97	80	0				
CB A6	lateral	4/VCP	6/16/97	50	0	6/16/97	50	0				
CB A7	mainline	10/VCP	6/12/97	20	17	6/13/97	20	17	9/2/97	37	0	Not accessible for complete 1st & 2nd line cleaning - debris
MH A1	MH A2	12/VCP	5/21/97	205	0	5/29/97	205	0				
MH A2	MH A3	12/VCP	5/21/97	200	0	5/29/97	200	0				
MH A3	MH A4	12/VCP	5/22/97	200	0	5/29/97	200	0				
MH A3	lateral	10/VCP	6/13/97	100	0	6/13/97	100	0				
MH A4	CB A5	18/VCP	6/12/97	200	0	6/16/97	200	0	,			
MH B1	CB B1-1	10/VCP	5/21/97	45	0	5/29/97	45	0				
MH B1	mainline	10/VCP	5/21/97	100	0	5/29/97	100	0				
MH B1	lateral	4/CIP	5/23/97	80	0	6/13/97	80	0				
MH B1	lateral	4/CIP	5/23/97	50	0	6/13/97	50	0				

TABLE B-10 (a) BASIN X STORM DRAIN LINE CLEANING SUMMARY LOG

From:	To:	Pipe Dia. (in)/	1st Clean-up	Cleaned	Uncleaned	2nd Clean-up	Cleaned	Uncleaned	3rd Clean-up	Cleaned	Uncleaned	
MH/CB	MH/CB	Type of Pipe	Date	(ft)	(ft)	Date	(ft)	(ft)	Date	(ft)	(ft)	Remarks
1	CB E5(8)										1	
CB A1	(Basin 8)	8/VCP	3/26/97	137	0	4/2/97	137	0	4/17/97	137	0	
CB A2	CB A1	12/VCP	3/27/97	125	0	4/3/97	125	0	4/17/97	125	0	
CB A2	CB A2-1	15/VCP	3/27/97	205	0	4/3/97	205	0	4/17/97	205	0	
CB A2-2	CB A2-1	12/VCP	3/27/97	137	0	4/2/97	137	0	4/17/97	137	0	
CB A3	MH B1	12/VCP	3/27/97	80	0	4/3/97	80	0				
CB A3	CB A4	10/VCP	3/27/97	155	0	4/2/97	155	0	4/17/97	155	0	
CB A3	CB A2	15/VCP	3/31/97	180	0	4/3/97	180	0	4/17/97	180	0	
CB A4	CB A5	8/VCP	3/27/97	155	0	4/2/97	155	0				
CB D2-1	CB D2	8/CIP	3/31/97	36	10	4/24/97	46	0				
CB D2-1	lateral	6/CIP	3/31/97	37	0	4/28/97	37	0				
CB D3-1	CB E4	8/Iron	4/1/97	100	0	4/3/97	100	0				
CB D3-1	CB D3	10/Corr	4/1/97	93	0	4/3/97	93	0	4/18/97	93	0	
CB E2-1	CB E2	6/VCP	3/31/97	30	0	4/28/97	30	0				
CB E2-1	lateral	4/CIP	4/2/97	40	0	4/28/97	40	0				
CB E3	lateral	4/CIP	4/2/97	29	0	4/28/97	29	0				
CB E4	CB E6	8/Corr.	4/1/97	75	0	4/3/97	75	0	4/18/97	75	0	
CB E5(8)	CB E4(8)				-						1	
(Basin 8)	(Basin 8)	8/VCP or CORR	3/26/97	137	0	4/2/97	137	0	4/17/97	137	0	
CB E9		İ									1 1	
(Basin 8)	CB FI	8/VCP	3/26/97	133	0	4/2/97	133	0	4/17/97	133	0	
CB F1	CB A2-2	10/VCP	3/27/97	137	0	4/2/97	137	0			1	
MH B1	MH B2	10/VCP	3/27/97	15	00	4/3/97	15	0			ļ	
MH B2	CB B2-2	8/VCP	3/27/97	70	0	4/3/97	70	0				
MH B2	CB B2-1	8/VCP	3/27/97	86	0	4/3/97	86	0				
MH C1	CB C1-1	10/Corr.	4/1/97	73	0	4/3/97	73	0		<u></u>		
MH C1	MH C2	10/Согт	4/1/97	145	0	4/3/97	145	0	4/18/97	145	0	
MH C1	CB C1-2	8/Corr.	4/3/97	79	0	4/18/97	79	0				
MH C2	CB C2-2	6/Соп.	4/1/97	75	0	4/3/97	75	0	4/18/97	75	0	
MH C2	CB C2-1	8/Corr	4/1/97	72	0	4/3/97	72	0	4/18/97	72	0	

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH A1	12/16/96, 12/17/96, 1/21/97	PASS
CB A1	12/16/96*	PASS
MH A2	12/16/96, 12/17/96, 1/21/97, 1/24/97, 1/28/97	PASS
CB A2	12/16/96*	PASS
CB A2-1	12/16/96, 1/21/97, 1/28/97	PASS
CB A2-2	12/16/96, 1/21/97, 1/28/97	PASS
MH A3	12/16/96, 12/17/96, 1/21/97, 1/24/97, 1/28/97	PASS
CB A3	12/16/96*	PASS
CB A3-1	12/16/96, 1/21/97	PASS
CB A3-2	12/16/96*, 1/21/97	PASS
MH A4	12/17/96, 1/28/97	PASS
MH A5	12/23/96, 1/13/97, 1/27/97, 1/28/97	PASS
CB A5	12/17/96*	PASS
MH A6	12/13/96, 12/23/96, 1/13/97, 1/14/97, 1/27/97, 1/28/97	PASS
CB A6	12/13/96*	PASS
MH A6-1	12/13/96, 1/14/97, 1/24/97	PASS
CB A6-1	12/13/96*, 1/27/97	PASS
MH A6-2	12/13/96, 1/24/97	PASS
CB A6-2	12/13/96*	PASS
CB A6-3	12/13/96*, 1/24/97	PASS
MH A6-3	12/13/97, 1/24/97	PASS
MH A6-4	12/26/96, 1/13/97, 1/27/97	PASS
CB A6-4	12/23/96*	PASS
MH A6-5	12/23/96, 12/26/96, 1/13/97, 1/27/97	PASS
CB A6-5	12/23/96*	PASS
MH A6-6	12/23/96, 12/26/96, 1/27/97	PASS
CB A6-6	12/23/96*	PASS
CB A6-7	12/23/96*, 12/23/96, 1/27/97	PASS
CB A6-8	12/23/96*, 1/27/97	PASS
CB A7	1/27/97	PASS
MH A7	1/13/97, 1/14/97	PASS
MH A7-1	1/16/97	PASS
CB A7-1	12/26/96*	PASS
MH A7-2	1/14/97, 1/15/97, 1/16/97, 1/27/97	PASS
CB A7-2	12/26/96*	PASS
MH A7-3	12/26/96, 1/14/97, 1/27/97	PASS
CB A7-3	12/26/96*	PASS
MH A7-4	12/26/96	PASS
MH A7-5	12/26/96	PASS
DIV. STRUCT. "B"	1/14/97, 4/30/97	PASS
MH B1	1/14/97, 1/16/97, 1/21/97*	PASS
CB B1-1	1/14/97, 1/16/97	PASS
MH B1-2	5/8/97, 5/9/97	PASS
CB B2	1/14/97*	PASS

MH - MANHOLE CB - CATCH BASIN

^{* -} INDICATES SEDIMENT TRAP

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB B3	1/14/97*	PASS
CB B4	1/14/97*	PASS
MH B4	1/14/97, 1/15/97	PASS
CB B4-1	1/15/97*	PASS
MH B5	1/15/97*	PASS
CB B6	1/15/97*	PASS
MH B6	1/15/97, 2/4/97	PASS
CB B6-1*	2/13/97	PASS
MH B7	2/4/97	PASS
MH B8	4/22/97	PASS
CB B8-1	5/14/97, 6/17/97	PASS
CB B8-2	5/14/97, 6/17/97	PASS
CB B8-3	4/22/97	PASS
CB B8-4	4/23/97	PASS
CB B8-5	4/22/97	PASS
MH B8-6	4/23/97	PASS
CB B7*	2/13/97	PASS
CB B8*	2/13/97	PASS
MH B9	4/17/97, 4/18/97	
CB B13	4/22/97	PASS
CB B14	5/14/97	PASS
OB B14	3/14/9/	PASS PASS
CB C1	1/16/97*	PASS
CB C2	1/16/97*, 5/2/97, 5/13/97	PASS
MH C2	1/16/97, 1/21/97	PASS; jack hammer used to expose
CB C2-1	5/2/97, 5/13/97	PASS
CB C2-2	5/5/97, 5/6/97	PASS
CB C2-3	5/5/97, 5/6/97	PASS
CB C2-4	5/5/97, 5/6/97	PASS
CB C2-5	5/5/97, 5/6/97	PASS
CB C3	1/16/97*, 5/6/97, 5/13/97	PASS
CB C4	1/16/97*, 5/6/97, 5/13/97	PASS
CB C5	1/30/97*, 5/6/97, 5/9/97	PASS
CB C6	5/6/97, 5/13/97	PASS
CR E1	47/07 5/0/07	
CB E1	4/7/97, 5/6/97	PASS
MH E2	2/3/97	PASS
MH E2-1	2/5/97, 5/1/97	PASS
MH E2-2	5/6/97, 5/7/97	PASS
CB E2-3	5/6/97, 5/9/97	PASS
CB E2-4	5/6/97, 5/7/97	PASS
CB E3	1/30/97*, 2/3/97	PASS
MH E4	1/30/97, 2/3/97	PASS
MH E4-1	1/30/97	PASS
MH E5	1/30/97, 2/3/97	PASS

MH - MANHOLE CB - CATCH BASIN

^{* -} INDICATES SEDIMENT TRAP

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB E6	1/30/97*, 2/3/97, 4/7/97	PASS
CB E7	1/30/97*, 2/3/97	PASS
CB E9	2/4/97	PASS
CB E10	2/4/97	PASS
CB E11	2/4/97	PASS
CB E13	2/3/97, 2/4/97	PASS
MH E14	2/5/97, 5/6/97	PASS
CB E15	2/3/97, 2/4/97	PASS
INLET E16	2/3/97, 5/7/97	PASS
MH E17	2/3/97	PASS
MH E18	2/3/97	PASS
CB F1	5/7/97	PASS
CB F2	5/8/97	PASS
CB F2-1	5/8/97	PASS
CB F3	5/6/97, 5/13/97	PASS
CB F4	5/8/97, 5/9/97	PASS
MH F5	5/9/97, 5/22/97	PASS
MH F6	5/12/97, 5/28/97	PASS
MITTO		
MH G1	1/16/97, 1/21/97	PASS
CB G1	1/16/97	PASS
MH G2	1/16/97, 1/21/97	PASS
CB G2	1/16/97*	PASS
MH I1	2/5/97	PASS
CB 11	2/6/97*	PASS
MH I2	2/5/97	PASS
CB 12	2/6/97*	PASS
MH 13	2/5/97, 2/6/97	PASS
CB 13	2/6/97*	PASS
MH 14	2/5/97	PASS
CB 14*	2/10/97	PASS
CB 15	2/5/97, 2/6/97	PASS
CB 16	2/6/97	PASS
MH 17	2/6/97	PASS
MH 18	2/6/97	PASS
CB 18*	2/10/97	PASS
MH 18-1	2/6/97	PASS
MH 18-2	2/6/97	PASS
CB 18-2*	2/10/97	PASS
CB 18-3	2/10/97, 5/1/97	PASS
CB 18-4	2/10/97, 5/1/97	PASS
CB 18-5	2/10/97, 5/1/97	PASS
MH 19	2/12/97, 5/5/97	PASS

MH - MANHOLE CB - CATCH BASIN

^{* -} INDICATES SEDIMENT TRAP

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB 19	2/10/97, 5/1/97	PASS
CB 19-1	2/10/97, 5/1/97	PASS
CB 19-2	2/12/97, 5/5/97	PASS
MH 19-3	2/10/97	PASS
MH I10	2/12/97, 6/17/97	PASS
MH I11	2/12/97, 5/1/97	PASS
CB I11-1	2/12/97, 5/1/97	PASS
MH I12	2/18/97	PASS
CB 112*	2/12/97	PASS
MH 113	2/12/97	PASS
MH I13-1	2/12/97, 5/2/97	PASS
CB 114	5/6/97, 6/17/97	PASS
CB 114-1	3/397	PASS
CB I14-2	2/13/97	PASS
CB I14-3	2/13/97	PASS
CB I14-4	2/13/97	PASS
CB 114-5	2/13/97	PASS
CB I14-6*	2/13/97	PASS
CB 114-7*	2/13/97	PASS
CB I16	5/14/97	PASS
CB J1	2/21/97	PASS
MH J2	2/20/97, 3/31/97	PASS
MH J2	2/20/91 , 3/3 (/91	1 700
CB K4	5/21/97	PASS
CB K3	5/21/97, 6/17/97	PASS
CB K5	5/21/97, 6/17/97	PASS
CB L1	5/7/97	PASS
MH L2	5/20/97	PASS
CB L3	5/20/97	PASS
CB L6	5/7/97, 5/15/97	PASS
CB L7	5/7/97	PASS
MH L7-1	5/7/97	PASS
CB L8	5/7/97, 5/15/97	PASS
CB L9	5/7/97, 5/15/97	PASS
MH L10	5/7/97, 5/15/97	PASS
WITETO		
CB M3	4/23/97, 5/2/97	PASS
CB M3-1	4/23/ 97, 5/2/97	PASS
MH N1	5/14/97, 6/17/97	PASS
CB N1-1	5/14/97	PASS
CB N2	5/14/97, 6/17/97	PASS
MH N3	5/14/97	PASS

MH - MANHOLE
CB - CATCH BASIN
* - INDICATES SEDIMENT TRAP
AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH P1	5/5/97, 5/6/97	PASS
CB P1-1	5/7/97, 6/17/97	PASS
CB P3	5/8/97, 5/9/97	PASS
MH P4	5/8/97, 5/9/97	PASS
CB G5		FILLED WITH SOIL
CB K8	. ••	NOT ACCESSIBLE FOR CLEANING
CB K6	• •	NOT ACCESSIBLE FOR CLEANING
CB K7	• •	NOT ACCESSIBLE FOR CLEANING
CB E19	• •	NOT ACCESSIBLE FOR CLEANING
CB I16-1	•-	NOT ACCESSIBLE FOR CLEANING
CB I18	••	NOT ACCESSIBLE FOR CLEANING
CB M1	••	NOT ACCESSIBLE FOR CLEANING
CB M2	••	NOT ACCESSIBLE FOR CLEANING
CB G2-1		NOT ACCESSIBLE FOR CLEANING
CB Q1	••	SUBMERGED
MH D2		SUBMERGED
CB D1	••	SUBMERGED
MH D6	••	SUBMERGED
CB D3		SUBMERGED
MH D3-1	••	SUBMERGED
MH D4	• •	SUBMERGED
CB D5		SUBMERGED
MH H1		SUBMERGED
MH H2	* *	SUBMERGED
MH H6		SUBMERGED
MH H3	••	SUBMERGED
MH H5		SUBMERGED
MH H4	••	SUBMERGED
CB L3-1		
CB L4		SUBMERGED
CB L5		SUBMERGED SUBMERGED
CB H7		
CB B9-1		SUBMERGED
CB B9-1		SUBMERGED
D.S. "J"	"	SUBMERGED
CB J3		SUBMERGED
		SUBMERGED
CB J4		SUBMERGED
MH J5		SUBMERGED
MH J5-1		SUBMERGED
MH B10		SUBMERGED
CB B10-1	 	SUBMERGED
MH B12		SUBMERGED
MH B11	<u></u>	SUBMERGED
CB B11-1	••	SUBMERGED

MH - MANHOLE

CB - CATCH BASIN

* - INDICATES SEDIMENT TRAP

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH G4		SUBMERGED
CB G4	• •	SUBMERGED
CB G4-1	- •	SUBMERGED
CB N4		SUBMERGED
CB G3	• •	SUBMERGED
CB A11		SUBMERGED
MH A9		SUBMERGED
CB A10		SUBMERGED

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH A1	11/6/96, 12/18/96,1/9/97	PASS
MH A1-1	12/18/96, 12/19/96, 1/6/97	PASS
MH A1-2	12/18/96	PASS
MH A1-3	12/18/96	PASS
CB A1-4	11/4/96	PASS
CB A1-X	1/2/97*	PASS
CB A1-Y	1/2/97	PASS
MH A1-Z	12/18/96, 1/7/97	PASS
MH A2	11/6/96, 12/18/96, 1/9/97	PASS
MH A3	11/6/96, 12/18/96, 1/9/97	PASS
CB A3-1	11/5/96*, 1/9/97	PASS
MH A4	11/6/96, 12/18/96, 1/9/97	PASS
CB A4-1	11/5/96*, 11/6/96, 1/9/97	PASS
CB A4-2	11/6/96, 12/19/96*, 1/9/97	PASS
CB A4-3	1/6/97	PASS
GT A4-4	1/6/97	PASS
MH A5	11/6/96, 11/27/96, 1/6/97	PASS
CB A5-0	11/7/96, 11/18/96	PASS
MH A5-1	11/7/96, 11/27/96	PASS
MH A5-2	11/7/96, 11/26/96, 1/6/97	PASS
CB A5-3	1/24/97	PASS
MH A5-4	11/6/96, 11/27/96, 1/6/97	PASS
		PASS, Located under a trailer: unable to clean
CB A5-5	11/6/96, 11/26/96, 12/19/96*	upstream drainage structures.
MH A6	11/7/96, 11/29/96, 12/2/96	PASS
CB A6-1	11/18/96*	PASS
CB A6-2	11/18/96*	PASS
CB A6-3	11/18/96*	PASS
CB A6-4	11/18/96*	PASS
CB A6-5	11/18/96*	PASS
MH A7	12/3/96, 12/4/96, 1/7/97	PASS
CB A7-1	1/7/97	PASS
MH A8	12/27/96, 12/30/96	PASS
MH A9	12/30/96	PASS
CB B1	11/5/96*, 1/9/97	PASS
CB B2	11/5/96*, 1/9/97	PASS
CB B3	11/5/96*	PASS
CB C1	11/5/96*	PASS
CB C2	11/5/96*, 11/6/96	PASS
MH C3	11/6/96, 11/26/96, 1/7/97	PASS
CB C4	11/5/96*	PASS

MH - MANHOLE CB - CATCH BASIN GT - GREASE TRAP

^{* -} INDICATES SEDIMENT TRAP

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB C5	11/5/96*	PASS
CB C6	11/26, 11/6	PASS
MH D1	11/12/96, 12/2/96, 1/9/97*	PASS
CB D2	11/18/96*, 11/27/96, 1/9/97*	PASS
CB D3	11/12/96, 11/18/96*, 1/6/97	PASS
CB D4	11/18/96*, 11/12/96	PASS
CB D5	11/12/96, 11/18/96*	PASS
CB D6	11/18/96*	PASS
MH D7	11/12/96, 12/2/96, 12/18/96	PASS
CB D8	11/12/96*, 12/18/96	PASS
CB D9	11/18/96*	PASS
CB D10	11/18/96*, 11/27/96, 12/18/96	PASS
		PASS
CB E1	11/7/96*, 1/8/97	PASS
CB E2	11/7/96*, 1/8/97	PASS
		PASS
CB F1	12/3/96*, 12/18/96	PASS
CB F2	12/3/96*	PASS
CB F3	12/3/96*	PASS
		PASS
CB G1	11/18/96*	PASS
CB G2	11/18/96*	PASS
CB G3	11/18/96*, 11/29/96*	PASS
CB H1	12/11/96	PASS
CB H2	12/11/96	PASS
CB H3	12/11/96*, 1/8/97	PASS
CB H4	12/11/96*, 1/8/97	PASS
CB H6	12/11/96*	PASS
CB H5	12/11/96*, 1/8/97	PASS
		PASS
CB I1	12/5/96	PASS
CB I2	12/5/96	PASS
CB 13	12/5/96	PASS
CB I4	12/4/96*, 12/5/96	PASS
CB 15	12/5/96*	PASS
CB A5-6		Filled with soil. Unable to clean catchbasin and upstream drainage structure.
CB A5-7		Filled with soil
CB A5-8		Filled with soil
CB A5-9		Filled with soil

MH - MANHOLE **CB - CATCH BASIN**

GT - GREASE TRAP

* - INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB A1	12/12/97*, 1/9/97	Pass; walls look like exposed aggregate, possible degredation from debris.
CB A2	12/12/97*, 1/9/97	Pass; walls look like exposed aggregate, possible degredation from debris.
CB A3	12/12/97*	Pass; walls look like exposed aggregate, possible degredation from debris.
MH A3	12/12/97, 1/9/97	Pass
CB A3-1	12/12/97*	Pass; walls look like exposed aggregate, possible degredation from debris.
MH A4	12/12/97, 1/9/97	Pass
CB A4-1	12/12/97*, 1/9/97	Pass; walls look like exposed aggregate, possible degredation from debris.
CB A4-2	12/12/97*, 1/9/97	Pass; walls look like exposed aggregate, possible degredation from debris.
CB A4-3	12/12/97*, 1/9/97	Pass; walls look like exposed aggregate, possible degredation from debris.
CB A5-1	12/12/97*	Pass; walls look like exposed aggregate, possible degredation from debris.
CB B1	1/9/97	Pass
CB B2	1/9/97*	Pass
CB C1	1/13/97	Pass
CB C2	1/13/97	Pass
CB D1	1/9/97*	Pass
CB D2	1/9/97*	Pass
MH A5	• •	Manhole has no bottom

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH B5	11/20/96, 1/7/97	PASS
MH B5-1	11/20/96, 1/7/97	PASS
CB B5-2	11/21/96*	PASS
CB B5-3	2/18/97, 2/19/97,	PASS
CB B5-4	2/18/97, 2/19/97	PASS
MH B5-5	5/20/97	PASS
MH B6	10/17/96, 11/21/96, 11/25/96, 11/29/96, 1/7/97	PASS
CB B6-1	11/29/96, 1/7/97	PASS
MH B6-2	10/17/96, 1/7/97	PASS
CB B6-3	10/17/96, 1/7/97, 2/3/97	PASS
MH B6-4	10/17/96	PASS
MH B6-5	10/17/96, 1/7/97, 2/3/97	PASS
MH B6-6	10/17/96	PASS
CB B6-7	11/29/96, 1/7/97	PASS
CB B6-8	11/25/96, 1/7/97	PASS
CB B6-9	11/25/96, 1/7/97	PASS
DIVERSION STRUCTURE	11/25/96, 1/7/97	PASS
MH B7	10/22/96, 10/23/96, 11/26/96, 1/8/97, 2/3/97	PASS
CB B7-1	1/8/97, 2/3/97	PASS
CB B7-2	1/8/97, 2/3/97	PASS
CB B7-3	1/8/97	PASS
CB B7-4	1/8/97, 2/3/97	PASS
CB B7-5	1/8/97, 2/3/97	PASS
CB B7-6	1/8/97, 2/3/97	PASS
CB B7-7	1/8/97, 2/3/97	PASS
CB B7-8	1/8/97*	PASS
MH B8	11/26/96, 1/8/97, 2/21/97	PASS
CB B8-1	11/20/96, 2/21/97	PASS
MH B8-2	11/20/96, 1/28/97, 1/29/97, 1/30/97	PASS
MH B8-3	11/20/96, 1/29/97*	PASS
MH B8-4	11/20/96, 1/29/97	PASS
CB B8-5	11/20/96, 1/29/97	PASS
CB B8-6	11/20/96, 1/29/97	PASS
CB B8-7	1/29/97*	PASS
CB B8-8	1/29/97*, 1/30/97	PASS
CB B8-9	2/12/97	PASS
MH B9	11/26/97, 1/8/97	PASS
CB D1	1/29/97*, 1/30/97	PASS
CB D2	1/29/97*, 1/30/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB E1	12/2/96*	PASS
CB E2	12/2/96*	PASS
CB E3	12/2/96*	PASS
CB E4	12/2/96*, 1/13/97, 2/3/97	PASS
CB E5	12/2/96*, 1/13/97, 2/3/97	PASS
CB F1	1/30/97	PASS
CB F2	1/30/97	PASS
CB F3	1/29/97*, 1/30/97	PASS

MH - MANHOLE
CB - CATCH BASIN
* - INDICATES SEDIMENT TRAP AND
RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH A1	2/10/97, 3/19/97	PASS
CB A1-1	4/9/97, 4/8/97	PASS
MH A1-2	4/9/97, 4/8/97	PASS
MH A1-3	4/9/97, 4/8/97	PASS
CB A2	2/10/97, 3/19/97	PASS
CB A3	2/10/97, 3/19/97	PASS
CBA4	2/10/97, 3/19/97	PASS
MH A5	2/10/97, 3/24/97, 4/14/97	PASS
CB A5-1	2/10/97, 3/19/97	PASS
CB A5-2	2/6/97*	PASS
CB A6	2/11/97, 4/15/97	PASS
ST A6-X	2/11/97, 4/15/97	PASS
CB A7	2/10/97, 3/19/97, 4/3/97	PASS
MH A-8 (DS "A")	2/10/97, 4/2/97	PASS
CB B1	3/10/97, 3/31/97	PASS
CB B1-1	3/10/97, 4/2/97	PASS
CB B1-2	3/10/97, 3/31/97, 4/1/97	PASS
CB B2	3/12/97, 3/18/97	PASS
CB B3	3/12/97, 3/18/97	PASS
CB B3-1	3/12/97, 3/17/97	PASS
CB B3-2	3/13/97, 3/17/97, 4/14/97	PASS
CB B4	4/9/97	PASS
CB B5	3/26/97, 3/31/97, 4/4/97	PASS
MH B5-1	3/26/97, 3/31/97, 4/4/97	PASS
CB B6	3/5/97	PASS
CB B6-1	3/5/97	PASS
CB B6-2	3/6/97, 3/25/97	PASS
CB B6-3	3/10/97, 4/1/97	PASS
CB B6-4	2/11/97, 4/2/97	PASS
CB B6-5	2/27/97	PASS
CB B6-6	3/4/97, 3/5/97	PASS
CB B6-7	2/27/97	PASS
CB B6-8	3/4/97, 3/6/97	PASS
CB B6-9	2/26/97	PASS
CB B6-10	3/4/97, 3/6/97	PASS
CB B6-11	3/4/97	PASS
CB B6-12	3/4/97, 3/5/97	PASS
CB B6-13	3/4/97, 3/5/97	PASS
CB B6-14	3/6/97, 3/25/97	PASS
CB B6-Y	2/11/97, 4/2/97	PASS
CB B7	3/10/97, 3/19/97, 3/25	PASS
CB B7-1	3/27/97, 4/4/97	PASS
CB B7-2	3/27/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB B8	2/25/97, 3/25/97, 4/4/97	PASS
CB B8-1	2/24/97, 3/26/97	PASS
CB B8-2	2/24/97, 3/26/97	PASS
CB B9	2/25/97, 3/6/97, 4/4/97	PASS
CB B9-1	2/24/97, 3/13/97	PASS
CB B9-2	2/24/97, 3/13/97	PASS
CB B9-3	2/24/97, 3/13/97	PASS
CB B10	2/12/97, 3/5/97, 4/11/97	PASS
CB B10-1	4/9/97	PASS
CB B10-2	2/12/97, 3/5/97	PASS
CB B10-4	2/12/97, 3/5/97	PASS
CB B10-5	2/12/97, 3/5/97	PASS
CB B10-6	2/12/97, 3/5/97	PASS
CB B10-7	2/12/97, 3/5/97	PASS
00.01	2/27/97	PASS
CB C1		
CB C2	2/27/97, 3/4/97	PASS
CB C3	2/27/97, 3/4/97	PASS
MH C4	2/27/97, 3/4/97	PASS
MH C5	3/3/97, 3/4/97	PASS
MH C6	3/3/97, 3/4/97, 4/4/97	PASS
MH C7	3/3/97, 3/4/97, 4/4/97	PASS
MH D1	2/26/97, 3/13/97	PASS
CB D1-1	2/26/97, 3/13/97	PASS
CB D1-2	2/25/97, 3/13/97, 3/26/97	PASS
CB D1-3	3/4/97, 4/1/97	PASS
CB D2	2/26/97, 3/24/97, 4/11/97	PASS
CB D2-1	2/26/97, 3/24/97, 4/11/97	PASS
CB D2-2	2/27/97, 3/24/97	PASS
MH D3	2/27/97, 4/2/97	PASS
CB D3-1	2/27/97, 4/2/97	PASS
CB D4	2/26/97	PASS
CB D5	2/26/97*	PASS
CB D6	4/8/97, 4/9/97	PASS
10154	0/4/07 0/6/07	PASS
MH E1	3/4/97, 3/6/97	
MH E2	3/4/97, 3/6/97	PASS
MH E3	4/8/97	PASS
CB E3-1	4/8/97	PASS
CB E4	3/5/97, 3/31/97	PASS
CB E4-1	3/3/97*	PASS
CB E4-2	3/5/97, 3/31/97	PASS
CB E5	3/5/97, 3/31/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB E6	3/3/97	PASS
CB E7	3/3/97	PASS
MH F-1	3/4/97, 3/5/97	PASS
CB F2	3/4/97, 3/5/97	PASS
CB F2-1	3/4/97, 3/5/97	PASS
CB F2-2	3/3/97, 3/5/97	PASS
CB G-1	3/18/97, 3/31/97	PASS
CB G-2	3/18/97, 3/31/97	PASS
CB G3	3/27/97, 4/1/97, 4/3/97	PASS
CB G-4	3/17/97	PASS
CB G-5	3/17/97	PASS
CB G-6	3/17/97	PASS
CB G-7	3/24/97	PASS
CB G8	3/27/97, 4/1/97	PASS
CB H1	3/27/97, 4/1/97	PASS
CB H2	3/27/97, 4/1/97	PASS
CB H2-1	3/27/97, 4/1/97	PASS
CB H2-2	3/25/97, 3/27/97, 4/1/97	PASS
CB I1	3/12/97, 3/31/97	PASS
CB I1-1	3/12/97, 3/31/97	PASS
CB I2	3/27/97, 3/31/97	PASS
CB 13	4/8/97	PASS
CB D3-2		NONFUNCTIONAL CATCHBASIN

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB A1	10/21/96*, 10/24/96	PASS
CB A1-1	10/21/96*, 2/20/97, 3/13/97	PASS
CB A1-2	10/21/96*, 10/24/96*, 2/20/97, 3/13/97	PASS
CB A1-3	10/21/96*, 10/24/96*, 2/20/97	PASS
CB A1-4	10/20//96*, 10/24/96*, 2/20/97	PASS
CB A1-5	10/24/96*, 10/28/96	PASS
CB A2	10/24/96*, 10/25/96, 11/15/96, 2/26/97	PASS
CB A2-1	10/24/96*	PASS
CB A3	10/25/96*, 11/15/96	PASS
CB A4	10/25/96, 10/28/96*, 10/30/96, 11/15/96, 11/25/97	PASS
CB A4-1	10/25/96*, 2/20/97, 3/13/97	PASS
CB A4-2	10/25/96, 2/20/97, 3/13/97	PASS
CB A4-3	10/28/96*	PASS
CB A4-4	10/28/96*, 11/15/96, 3/13/97, 3/17/97	PASS
CB A4-5	10/28/96*, 11/15/96, 3/13/97, 3/17/97	PASS
CB A4-6	2/13/97*	PASS
CB A5	10/30/96*, 11/25/97, 2/21/97	PASS
MH A5-1	2/13/97, 2/19/97, 2/25/97	PASS
MH A5-2	2/13/97, 2/19/97, 2/25/97	PASS
CB A5-3	2/13/97, 2/19/97	PASS
CB A6	10/30/96, 11/4/96, 11/13/96, 11/14/96*, 3/17/97, 4/3/97	PASS
CB A6-1	11/4/96*, 11/13/96, 11/14/96, 3/13/97, 4/2/97	PASS
CB A6-2	11/4/96*, 11/14/96, 3/13/97, 4/2/97	PASS
CB A6-3	11/4/96, 2/21/97, 4/2/97,	PASS
CBA 6-4	11/4/96*, 2/24/97, 4/15/97	PASS
CB A6-5	11/14/96*	PASS
DIVERSION STRUCTURE	11/13/96	PASS
MH A7	11/13/96, 2/24/97, 2/25/97	PASS
CB A7-1	11/13/96, 2/24/97, 2/25/97	PASS
CB A7-2	2/19/97	PASS
CB A7-3	2/19/97	PASS
CB A8	11/13/96, 11/14/96, 11/15/96*, 2/21/97, 2/25/97	PASS
CB A8-1	11/14/96*, 2/21/97, 2/25/97	PASS
CB A8-2	11/14/96, 2/18/97, 2/25/97	PASS
CB A9	11/13/96, 2/24/97	PASS
CB B1	11/13/96, 11/15/96, 2/21/97,	PASS
CB B2	11/13/96, 11/14/97*, 2/21/97	PASS
CB B3	11/13/96, 11/14/97*, 2/21/97	PASS
CB B4	11/13/96, 1/1/14/97 , 2/21/97	PASS
MH D1	2/24/97, 2/26/97	PASS
MH D1-1	2/21/97*	PASS
MH D1-2	2/21/97*	PASS
MH D2	2/24/97	PASS
CB D2-1	2/24/97	PASS
CB F1	3/18/97	PASS
CB C1	••	CATCHBASIN HAS NO BOTTOM

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB A1	5/12/97, 5/15/97	PASS
CB A2	5/12/97, 5/15/97	PASS
CB A2-1	4/29/97	PASS
CB A3	5/13/97, 5/15/97	PASS
CB A3-1	5/20/97, 5/28/97	PASS
MH A4	5/13/97, 5/15,97	PASS
CB A4-1	4/29/97	PASS
CB A4-2	6/10/97	PASS
MH A5	5/13/97, 5/15/97	PASS
CB A5-1	4/29/97	PASS
CB A5-2	4/29/97	PASS
CB A6	5/14/97, 5/15/97	PASS
CB A7	5/2/97	PASS
MH A8	5/14/97, 5/15/97	PASS
MH A9	5/15/97, 5/27/97	PASS
MH A10	5/15/97, 5/27/97	PASS
CB A10-1	5/15/97	PASS
CB A11-1	5/2/97	PASS
CB A12	6/11/97	PASS
CB A13	6/10/97	PASS
CB A15*	4/29/97	PASS
MH C12	5/12/97, 5/28/97	PASS
MH C12-1	5/12/97	PASS
CB C12-2	5/13/97, 5/28/97	PASS
CB C12-3	5/12/97, 5/28/97	PASS
CB E1	4/28/97, 5/19/97	PASS
CB E1-1	4/28/97.5/19/97	PASS
CB E1-2	4/28/97,5/19/97	PASS
MH E2	4/28/97,5/28/97	PASS
CB E2-1	4/28/97, 5/28/97	PASS
MH E3	4/28/97, 5/16/97	PASS
CB E3-1	4/29/97, 5/27/97	PASS
CB E3-2	4/29/97, 5/23/97	PASS
CB E3-3	4/28/97, 5/16/97	PASS
CB E3-4	4/29/97, 5/16/97	PASS
MH E4	4/29/97, 5/27/97	PASS
CB E4-1	4/29/97, 5/27/97	PASS
CB E4-2	4/24/97, 4/29/97, 5/27/97	PASS
CB E4-4	4/29/97, 5/16/97	PASS
CB E4-5	6/10/97, 6/11/97	PASS
MH E5	4/29/97	PASS
CB E5-1	4/29/97	PASS
MH E6	4/29/97, 5/27/97	PASS
IVII I LO	TIEGIGI, SIELIGI	I PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH E6-1	5/13/97, 5/28/97	PASS
MH E6-2	5/12/97	PASS
CB E6-3	5/14/97, 5/27/97	PASS
MH E6-4	5/13/97, 5/28/97	PASS
CB E7	5/13/97, 5/15/97	PASS
CB E7-1	5/13/97, 5/15/97	PASS
CB E7-2	5/13/97, 5/15/97	PASS
CB E8*	4/24/97	PASS
CB A9-1		NOT ACCESSIBLE FOR CLEANING
MH A11		NOT ACCESSIBLE FOR CLEANING
CB A14		NOT ACCESSIBLE FOR CLEANING
CB C11		NONFUNCTIONAL CATCHBASIN
CB C11-1		NONFUNCTIONAL CATCHBASIN
CB E4-3		FILLED WITH SOIL

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH A1	4/14/97, 4/21/97	PASS
MH A2	4/14/97	PASS
CB A2-1	4/14/97	PASS
MH A3	4/15/97	PASS
CB A3-1	4/15/97	PASS
MH A4	4/15/97	PASS
CB A4-1	4/17/97	PASS
MH A5	4/15/97	PASS
MH A6	4/15/97	PASS
MH A7	4/15/97	PASS
CB A7-1	4/18/97	PASS
MH A7-2	4/15/97	PASS
MH A8	4/23/97, 5/15/97	PASS
CB A8-1	4/24/97	PASS
MH A9	4/22/97	PASS
CB A9-1	4/15/97	PASS
MH A10	4/22/97, 5/5/97	PASS
MH A11	4/22/97, 5/5/97	PASS
CB A11-1*	4/15/97	PASS
MH A17	4/22/97	PASS
CB A19	4/17/97	PASS
CB A20	6/17/97	PASS
CB A21	4/15/97	PASS
CB A22	4/17/97	PASS
CB A23*	4/11/97	PASS PASS
MI D4	4/15/97	2400
MH B1		PASS
CB B1-1	4/15/97	PASS
MH B2	4/15/97	PASS
CB B2-1	4/15/97	PASS
MH B3	4/16/97, 4/30/97	PASS
CB B4	4/16/97, 4/30/97	PASS
CB B4-1	4/15/97, 4/30/97	PASS
CB B5	4/24/97, 5/14/97	PASS
CB B5-1*	4/15/97	PASS
CB B5-2*	4/15/97	PASS
CB B5-3*	4/11/97	PASS
CB B6	4/25/97, 4/30/97	PASS
MH B6-1	4/17/97, 5/21/97	PASS
MH B7	4/23/97, 5/5/97	PASS
CB B7-1	4/15/97	PASS
MH B7-2	4/23/97, 4/30/97	PASS
MH B8	4/23/97, 4/30/97	PASS
MH B9	4/21/97, 6/16/97	PASS
CB B10*	4/28/97	PASS
CB B11*	4/9/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB B12*	4/9/97	PASS
MH C1	4/16/97, 4/21/97	PASS
MH C2	4/16/97, 4/21/97	PASS
CB C2-1	4/16/97, 4/21/97	PASS
CB C2-2*	4/21/97	PASS
MH C3	4/16/97, 4/21/97	PASS
CB C3-1	4/16/97, 4/21/97	PASS
CB C3-2*	4/21/97	PASS
MH C4	4/15/97, 4/21/97	PASS
CB C4-1	4/15/97, 4/21/97	PASS
MH C5	4/15/97, 4/21/97	PASS
CB C5-1*	4/18/97	PASS
MH C6	4/16/97, 4/21/97	PASS
CB C6-1*	4/21/97	PASS
CB C6-2*	4/21/97	PASS
MH C7	4/16/97, 4/21/97	PASS
CB C7-1	4/21/97	PASS
CB C7-2*	4/21/97	PASS
CB C8*	4/18/97	PASS
CB C8-1*	4/21/97	PASS
CB C9	4/21/97	PASS
CB C9-1*	4/21/97	PASS
CB C10*	4/18/97	PASS
MH D1	4/15/97, 4/29/97	PASS
CB D2	4/15/97	PASS
CB D2-2	4/15/97, 4/29/97	PASS
MH E2	4/14/97, 4/29/97	PASS
MH E2-1	4/15/97, 4/29/97	PASS
CB E2-2	4/14/97, 4/29/97	PASS
CB E2-3	, 4/14/97, 4/29/97	PASS
MH E2-4	4/14/97, 4/29/97	PASS
CB E2-5	4/15/97, 4/29/97	PASS
MH E3	4/14/97, 5/29/97	PASS
CB E3-1	4/14/97, 4/29/97	PASS
CB E3-2	4/14/97, 4/29/97	PASS
CB E4*	4/7/97	PASS
CB E6*	4/7/97	PASS
CB E7*	4/7/97	PASS
CB E8	4/15/97, 6/16/97	PASS
CB E9*	4/7/97	PASS
DIVERSION STRUCTURE	4/23/97, 5/5/97	PASS
MH F1*	4/22/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB F1-1*	4/22/97	PASS
CB F2*	4/15/97	PASS
CB F2-1*	4/22/97	PASS
CB F3	4/17/97, 5/21/97	PASS
CB F4*	4/11/97	PASS
CB F5*	4/11/97	PASS
CB F6*	4/9/97	PASS
CB F7*	4/9/97	PASS
CB F8*	4/11/97	PASS
CB F9*	4/11/97	PASS
CB F10*	4/11/97	PASS
CB F11*	4/22/97	PASS
CB F12*	4/22/97	PASS
CB F14*	4/11/97	PASS
CB F15-1*	4/11/97	PASS
CB F16*	4/15/97	PASS
CB F19*	4/11/97	PASS
CB G1*	4/17/97	PASS
CB G2*	4/17/97	PASS
MH G4*	4/21/97	PASS
CB G5*	4/17/97	PASS
CB G6*	4/17/97	PASS
MH A6-1		NOT ACCESSIBLE FOR CLEANING
MH A6-2	• •	NOT ACCESSIBLE FOR CLEANING
MH A12	• •	NOT ACCESSIBLE FOR CLEANING
MH A13		NOT ACCESSIBLE FOR CLEANING
MH A14		NOT ACCESSIBLE FOR CLEANING
CB A15		NOT ACCESSIBLE FOR CLEANING
MH A16	• •	NOT ACCESSIBLE FOR CLEANING
MH A18		NOT ACCESSIBLE FOR CLEANING
MH C11		NOT ACCESSIBLE FOR CLEANING
MH F10-1		NOT ACCESSIBLE FOR CLEANING
CB F13	• •	NOT ACCESSIBLE FOR CLEANING
MH F15		NOT ACCESSIBLE FOR CLEANING
CB F18		NOT ACCESSIBLE FOR CLEANING

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
MH A1	5/21/97, 5/29/97	PASS
CB A1-1	5/16/97	PASS
MH A2	5/16/97, 5/30/97	PASS
CB A2-1	5/16/97	PASS
CB A2-2	5/16/97, 5/30/97	PASS
CB A2-3	5/16/97, 5/30/97	PASS
MH A3	5/21/97, 5/29/97, 6/13/97	PASS
CB A3-1	5/16/97	PASS
MH A4	5/22/97, 5/29/97	PASS
CB A4-1	5/16/97	PASS
CB A4-2	6/11/97, 6/13/97	PASS
CB A4-3	6/11/97	PASS
CB A5	6/12/97, 6/16/97	PASS
CB A5-1	6/12/97, 6/16/97	PASS
CB A6	6/16/97	PASS
CB A7	6/12/97, 6/13/97	PASS
MH B1	5/21/97, 5/29/97	PASS
CB B1-1	5/21/97, 5/29/97	·
CB B1-2	5/19/97	PASS
CB B1-2	5/19/9/	PASS
CB C11*	5/19/97	PASS
CB C12*	5/19/97	PASS
MH C1		MANHOLE HAS NO BOTTOM
MH C2		MANHOLE HAS NO BOTTOM
MH C3		MANHOLE HAS NO BOTTOM MANHOLE HAS NO BOTTOM
MH C4		
MH C5		MANHOLE HAS NO BOTTOM
MH C6		MANHOLE HAS NO BOTTOM
MH C7		MANHOLE HAS NO BOTTOM
MH C8	 	MANHOLE HAS NO BOTTOM
MH C9		MANHOLE HAS NO BOTTOM
	••	MANHOLE HAS NO BOTTOM
MH C10	<u> </u>	MANHOLE HAS NO BOTTOM

^{*-} INDICATES SEDIMENT TRAP AND
RELATED SEDIMENT/SLUDGE REMOVAL

CATCH BASIN/MANHOLE	DATE CLEANED	REMARKS
CB A1	4/17/97, 4/2/97, 3/26/97	PASS
CB A2	4/17/97, 4/3/97, 3/31/97	PASS
CB A2-1	4/17/97, 4/2/97, 3/27/97	PASS
CB A2-2	4/17/97, 4/2/97, 3/27/97	PASS
CB A3	4/17/97, 4/2/97, 3/27/97	PASS
CB A4	4/2/97, 3/27/97	PASS
CB A5	4/2/97, 3/27/97	PASS
MH B1	4/3/97, 3/27/97	PASS
MH B2	4/3/97, 3/27/97	PASS
CB B2-1	4/3/97, 3/27/97	PASS
CB B2-2	4/3/97, 3/27/97	PASS
MH C1	4/3/97, 4/1/97	PASS
CB C1-1	4/3/97, 4/1/97, 3/26/97	PASS
CB C1-2	4/3/97, 4/18/97	PASS
MH C2	4/18/97, 4/3/97, 4/1/97	PASS
CB C2-1	4/18/97, 4/1/97, 4/3/97	PASS
CB C2-2	4/18/97, 4/1/97, 4/3/97	PASS
CB D1	3/25/97	PASS
CB D2	3/31/97, 4/24/97	PASS
CB D2-1	3/31/97, 4/24/97	PASS
CB D3	4/18/97, 4/3/97, 4/1/97	PASS
CB D3-1	4/18/97, 4/3/97, 4/1/97	PASS
CB E1	5/1/97	PASS
CB E2	3/31/97, 4/28/97	PASS
CB E2-1	3/31/97, 4/28/97	PASS
CB E3	4/2/97, 4/28/97	PASS
CB E4	4/18/97, 4/3/97, 4/1/97	PASS
CB E5	4/17/97, 4/2/97, 3/26/97	PASS
CB E6	4/1/97, 4/3/97, 4/18/97	PASS
CB F1	4/2/97, 3/27/97	PASS

^{* -} INDICATES SEDIMENT TRAP AND RELATED SEDIMENT/SLUDGE REMOVAL